

09/02/22

DIRECT SETTLEMENT

CAR IN WORKSHOP / CAR NOT WORKSHOP

EMAIL : lawrenceteo@tanchong.com

H / P : 94568832 FAX : 64697472

OWNER'S NAME : CHUA CHIEW LAI (CAI QIULAI)
ADDRESS : 933 BUKIT TIMAH ROAD
#04-28
S(589644)
TELEPHONE NO : 94560617

TYPE OF CLAIM	:	DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO	:	TP-SHC8940Z
VEHICLE NO	:	SLW6793S
MODEL CODE	:	TDWARDZE12EDAY487Z
MODEL/YEAR	:	NOTE 1.2 BASE (IV) MY2017
ENGINE NO	:	HR12278151B
CHASSIS NO	:	JN1TAAE12Z0980248
MILEAGE	:	1 KM
DATE IN	:	09/07/2020
LIABILITY	:	0.00
EXCESS CLAUSE	:	0.00
ESTIMATE BY	:	LAWRENCE
ACCIDENT DATE	:	02/07/2020

no 2

vll.c/ot sck

Lick
~~lick~~
for
~~water~~
3.20 P

Rasur

- To survey before/after spray painting
- To display damaged part(s) during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary Item(s) must be surveyed and is subject to final approval from Insurance Company

Order

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLW6793S

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	✓
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 04	480.00	240
3	RS	SUPPLY & INSTALL REVERSE SENSOR OR R/I	55.00	✓
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	300.00	200
5	ZZ/001	REPAIR LH/RH REAR FENDER AND RENEW END PANEL, TAILGATE, REAR BUMPER	390 2000.00	975-1170
6	ZZ/002	S/PAINT REAR PORTION	1500.00	1000 - 1250
7	ZZ/003	CHECK LIGHTING	48.00	✓
8	ZZ/004	R/I REAR WINDSCREEN TO ASSIST REPAIR	150.00	✓
9	ZZ/005	R/I TAILGATE MECHANICAL PARTS TO NEW DOOR	60.00	✓
TOTAL LABOUR CHARGES			4713.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLW6793S

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1	CAMERA BRACKET / <i>acc</i>	BRACKET-CAM			20.00
2	EMBLEM NOTE / <i>acc</i>	90892-3VA0A	79.90		
3	EMBLEM-BACK DOOR NISSAN / <i>acc</i>	90890-3VA0A	64.90		
4	STRIKER-TAIL GA ?	90570-1HM0B	34.80		
5	A LOCK LIFT ?	90502-1HM1A	128.40		
6	WEATHER STRIP / <i>Cut</i>	90830-3VA0A	68.20		
7	DOOR BACK / <i>Buc</i>	K010M-3VAMA	1018.20		
8	GROMET BUMPER \$3.40 EA X 02 / <i>acc</i>	76881-3VA0A			6.80
9	GROMMET BUMPER \$2.70 EA X 02 / <i>acc</i>	63846-5V000	5.40		
10	STAY-RR BUMPER <i>LH</i> / <i>BT</i>	H5212-1HMMA	96.90		
11	ENERGY ABSORBER ?	85090-5WJ0A	125.30		
12	BRKT BUMPER RH X <i>NN</i>	85220-3VA0C	51.00		
13	BRKT BUMPER LH / <i>Re</i>	85221-3VA0C	51.00		
14	FACE-RR BUMPER / <i>Re</i>	85022-5WJ0H	460.00		
15	PLATE-LUGGAGE / <i>Re</i>	84992-3VA0A	68.80		
16	CROSSEAR REAR END PANEL LOWER ?	554B2-1A13B	731.30		
17	PANEL REAR <i>Repair</i>	79100-3VA0A	552.80		
18	CLIP BUMPER \$1.40 EA X 06 / <i>acc</i>	01553-09321	8.40		
19	CLOSING PLATE-LH ?	78819-5WJ0A	48.80		
20	ORNAMENT ASSY REAR LH BUMPER / <i>Re</i>	26560-5C000	61.90		
21	GROMET C/LAMP \$4.90 EA X 02 ?	26557-2U000	9.80		
22	GROMET C/LAMP \$4.90 EA X 02 ?	26557-2U001	9.80		
23	LAMP COMB RR, LH ?	26555-5WK0A	435.80		
24	REAR W/SCREEN SEALANT / <i>Re</i>	SEALANT - 4			80.00
25	SUNDRIES / <i>acc</i>	NPN			

20.

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO BLW67938

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
26	SENSOR-REVERSE / PM	SENSOR			250.00	
SUB TOTAL			4111.40	0.00	456.80	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			822.28	0.00	0.00	
GRAND TOTAL			3289.12	0.00	456.80	
OVERALL TOTAL			3745.92			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO 81W6791B

TOTAL LABOUR CHARGES	4713.00
TOTAL SPARE PARTS CHARGES	3745.92
GRAND TOTAL	8458.92 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS CLAUSE :

LIABILITY :

REMARKS :

Guo Qiang - 82880282

01/9/2020

0.00

0.00

before paint photos.

5-6 Days.

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.