

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

01/09/2020

OUR REF NO. SFG 4885D

TOMMY TEO WEI MING
BLK 63, NEW UPPER CHANGI ROAD,
#12-1176
SINGAPORE 461063

TP Budget Direct

Shirley

WDD2043472F873999

ESTIMATE BILL FOR VEHICLE NO. SFG 4885D MODEL : MERCEDES BENZ C250

LIST ITEM

1) REAR BUMPER	<i>torn</i>		\$ 2,688.00	<i>1453</i>
2) REAR BUMPER CLIP	<i>new</i>	10PCS @\$6.50	\$ 65.00	<i>30</i>
3) REAR BUMPER SIDE ATTACHEMENT	<i>RH and</i>	2PCS @\$114.00	\$ 228.00	<i>114</i>
4) REAR BUMPER SIDE GARNISH	<i>at</i>		\$ 286.00	<i>✓</i>
5) REAR BUMPER SIDE GARNISH	<i>clips</i>	4PCS @\$6.50	\$ 26.00	<i>✓</i>
6) REAR FENDER (RH)	<i>Repair</i>		\$ 1,946.00	<i>+</i>
7) REAR FENDER INNER BOARD (RH)	<i>new</i>		\$ 1,210.00	<i>+</i>
8) REAR FENDER INNER COWLING (RH)	<i>new</i>		\$ 293.00	<i>+</i>
9) REAR FENDER INNER COWLING CLIPS (RH)	<i>new</i>	5PCS @\$6.50	\$ 32.50	<i>+</i>
10) REAR FENDER QUARTER GLASS WITH MOULDING (RH)	<i>new</i>		\$ 1,121.00	<i>+</i>
11) REAR QUARTER GLASS TOP CHROME (RH)	<i>new</i>		\$ 547.00	<i>+</i>
12) REAR QUARTER GLASS BOTTOM CHROME (RH)	<i>new</i>		\$ 348.00	<i>+</i>
13) PETROL TANK DOOR	<i>Repair</i>		\$ 280.00	<i>X</i>
14) REAR WHEEL HOUSING PANEL (RH)	<i>Repair</i>		\$ 686.20	<i>+</i>
15) REAR KNUCKLE ARM (RH)	<i>new</i>		\$ 1,218.00	<i>+</i>
16) REAR KNUCKLE BEARING (RH)	<i>changed</i>		\$ 280.00	<i>✓</i>
17) REAR BEARING HUP (RH)	<i>changed</i>		\$ 348.00	<i>✓</i>
18) REAR LOWER ARM (RH)	<i>Best</i>		\$ 428.00	<i>✓</i>
19) REAR UPPER ARM (RH)	<i>Best</i>		\$ 284.00	<i>✓</i>
20) REAR TRADING ARM (RH)	<i>Best</i>		\$ 2,248.00	<i>315</i>
21) REAR CROSS MEMBER	<i>new</i>		\$ 2,863.00	<i>X</i>
22) REAR WINDSCREEN MOULDING	<i>new</i>		\$ 328.00	<i>X</i>
			\$ 17,753.70	
LESS DISCOUNT - 10%			\$ 1,775.37	
			\$ 15,978.33	

3564

3207.60

SPECIAL NETT ITEM1) REAR SPORT RIM (RH) *lit*2) REAR TYRE (RH) *new*

3) REAR QUARTER GLASS INNERSEAL

4) REAR QUARTER GLASS GUM

5) REAR WINDSCREEN INNERSEAL

6) REAR WINDSCREEN GUM

\$ 1,280.00 *700*\$ 450.00 *+*\$ 60.00 *+*\$ 60.00 *+*\$ 60.00 *+*\$ 60.00 *+*

\$ 1,970.00

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM

2) TO APPLY UNDERSEALING ON AFFECTED AREAS

3) TO MOUNT VEHICLE ON CAR O-LINER

4) TO CONDUCT 4 WHEEL ALIGNMENT

5) TO REMOVE AND REFIX PETROL TANK, PIPING SYSTEM

6) TO REMOVE AND REFIX REAR QUARTER GLASS (RH)

7) TO REMOVE AND REFIX FRONT WINDSCREEN ASSY

8) TO REMOVE AND REFIX FRONT UNDERCARRIAGE ASSY (RH)

9) TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC

10) TO RESPRAY ON AFFECTED AREAS

\$ 60.00 *30*\$ 120.00 *60*\$ 420.00 *+*\$ 120.00 *80*\$ 280.00 *+*\$ 280.00 *+*\$ 420.00 *+*\$ 660.00 *220*\$ 1,540.00 *500*\$ 880.00 *500*

\$ 4,780.00

GRAND TOTAL : \$ 22,728.33

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
*4/s 01/09/20**06 Days**total: 5297.60**4/s: 4.2k*