

English (default) ▼

LKK AUTO CONSULTANTS PTE LTD (OD) ▼



SERVICE REQUESTS

MESSAGES

CLAIMS



Service Request Details

Claim

S0M02SZ3

Reference

None

Loss Date

August 28, 2020

Report Date

Aug 29, 2020 12:00:00
AM

Request Date

September 1, 2020

Due Date

September 1, 2021

Vendor Name

LKK AUTO
CONSULTANTS PTE LTD
(OD)

Type of Loss

Own Damage

Services

Fire

Actions

Next Step
Finish the
workComplete
Work

More ▼

Vehicle Information

Incident Vehicle

Registration #
SLC5931Y

Make

HONDA

Model

VEZEL 1.5

Service Address

51 Ubi Avenue 1 #01-
25 Paya Ubi, , , 408933

Primary

Contact/Insured

SEE

KWAI YUE RAPHAEL
335 CHOA CHU KANG
AVENUE 3, #03-12,
689871,
Singapore 98578006
RAFSEE1162@GMAIL.COM

Claim Handler

HO

Winnie 6568804833
winnie.ho@axa.com.sg

Additional Instructions

OD-FIRE pls conduct investigation and apply SCDF report. Tks

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE 

SENT 9/2/20 4:13 PM

FROM LKK AUTO CONSULTANTS PTE LTD (OD)

SUBJECT [IA UPLOADED](#)

BODY [Hi, uploaded IA. Regards Denise](#)



TYPE 

SENT 9/1/20 10:16 AM

FROM HO Winnie

SUBJECT [SLC5931Y - FIRE](#)

BODY [Hi Naz, pls check if any modification / malfuncti...](#)

