

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Sep 2020 14:41 Edit Reg		01 Sep 2020 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: PEAPES FOOTWEAR PTE LTD , Co. Reg. No.: 200000359D									
Main Claimant: SBS TRANSIT LIMITED									
Vehicle Reg. No.: BICYCLERACK		Date of Loss:	14/05/2020 12:00 - :59						
Claim Type: TP PD		Policy/Cover Note No.:	0100180344 (Comprehensive)						
Vehicle Reg. No. (Insured): GU8053B		Policy No. (Claimant):							
		Excess:							
Repairer: - Not Applicable - (-)									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/10/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
AIG_SG_EXPRESS (22/09/2020): Alert - Adj Mandate Approved (S\$1712.00) - BICYCLERACK									
ALL ASSOCIATED TASKS ☐				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*BICYCLERACK
[GU8053B]
TP PD
SBS TRANSIT LIMITED
May 14 2020 12:00PM
[PEAPES FOOTWEAR PTE LTD]

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Letters/Correspondences			1 per page ▼ ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit
Assessment Reports			1 per page ▼ ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	(Draft)	Adjuster Final Report		(Protected)
Photos/Images			3 per page ▼ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	14/09/20 15:51	General View		Load JPG ☒
2	14/09/20 15:51	General View		Load JPG ☒
3	14/09/20 15:51	General View		Load JPG ☒
4	14/09/20 15:51	General View		Load JPG ☒
5	14/09/20 15:51	General View		Load JPG ☒
Documentation			1 per page ▼ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	14/09/20 15:50	Quotation		Load PDF
2	14/09/20 15:50	Police Report		Load PDF
3	14/09/20 15:50	EMAIL FROM AIG DD 10.09.2020		Load PDF
4	14/09/20 15:50	PRELI ADVISED		Load PDF
5	14/09/20 15:50	EMAIL TO AIG DD 10.09.2020		Load PDF
6	14/09/20 15:50	OI GIA REPORT		Load PDF
7	14/09/20 15:50	Status of Driving Licence - 11.09.2020		Load PDF
8	14/09/20 15:51	LETTER TO OI		Load PDF
9	25/09/20 17:22	Authorisation to Act		Load PDF
10	25/09/20 17:22	LOD		Load PDF
11	25/09/20 17:22	QUOTATION		Load PDF
12	25/09/20 17:22	Release Voucher		Load PDF
13	28/09/20 10:21	LKKInvoice		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.		

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GU8053B (Insd veh)	Model:	
	BICYCLERACK (TP veh)		
Date of Accident:	14/05/2020		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	
Final Repair Cost	:	\$	1,712.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum	:	\$	1,712.00
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ 100 _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	TAC CONTRACTS PTE LTD	: \$	1,712.00

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

28 Sep
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: [6256-3561](tel:6256-3561) Fax: [6844-8805](tel:6844-8805) Email: sur@lkkauto.com; assignments@lkkauto.com

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #07-16

Singapore 079120

25 Sep 2020

Attention:**FINAL REPORT**

YOUR REF : TBA

OUR REF : CC4/AIG20009248/GEA3S2

NAME & ADDRESS OF INSURED : PEAPES FOOTWEAR PTE LTD
Singapore

OCCUPATION :

POLICY NO : 0100180344

POLICY TERM : To be advised

POLICY COVERAGE : COMPREHENSIVE

TIME, DAY & DATE OF LOSS : Thursday, 14 May 2020

INSURED VEHICLE : bearing registration no. GU8053B

DRIVER : YEO TECK KWEE

THIRD PARTY : SBS TRANSIT LIMITED

TYPE OF ACCIDENT : INSURED DRIVER REVERSED AND HIT BICYCLE RACK

LOCATION OF ACCIDENT : 62 BUKIT TIMAH ROAD (BICYCLE BAY NEAR MRT)

RESERVE : S\$1,600.00 (provisional) + 7%GST = \$1,712.00

We refer to our First Advice of 07/09/2020 and now report further as follows:-

INSURED

PEAPES FOOTWEAR PTE LTD

THIRD PARTY

SBS TRANSIT LIMITED

SCENE

INSURED DRIVER REVERSED AND HIT BICYCLE RACK NEAR LITTLE INDIA MRT STATION

CIRCUMSTANCES

INSURED DRIVER REVERSED AND HIT BICYCLE RACK NEAR LITTLE INDIA MRT STATION

INVESTIGATION

- NIL -

POLICE

- NIL -

EXTENT OF INJURY AND DAMAGE

BICYCLE RACK DAMAGED

INSURED'S LIABILITY

- NIL -

POLICY LIABILITY

- NIL -

SUBROGATION

- NIL -

CONTRIBUTION

- NIL -

RESERVE

- NIL -

REMARKS

- A) TO HACK BASE OF AFFECTED RACK FOR REMOVAL WORKS.
- B) TO REMOVE EXISTING DAMAGED JACK THEREAFTER DISPOSE OFFSITE.
- C) TO FABRICATE, SUPPLY AND INSTALL NEW SS304, 12MM (THICK) x 100MM (WIDTH) x 600MM (HEIGHT) STAINLESS STEEL BICYCLE RACK AT ABOVE LOCATION. (EXACT MEASUREMENT TO BE DONE ON SITE BEFORE FABRICATION)
- D) TO CAST IN SITU CONCRETE TO EMBED NEWLY INSTALL BICYCLE RACK.
- E) TO DO GENERAL CLEANING UPON COMPLETION OF WORK.
- F) TO SUPPLY LABOUR, MATERIALS & EQUIPMENTS FOR THE ABOVE WORKS.

LKK Auto Consultants Pte Ltd