

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/INC20009253/Uqf3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

N/S	O/S

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / BUM / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

Date / Time

Action / Instruction

Date/Time, File Pass to?

11/0/09 Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum H.B. (\$) 7000

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

: Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation:

: S + RS, SI

: Photos

: Others

TOTAL

9/9/20 2/5 @ 7000 confirmed with Tony (Red \$8070.40, 54%)



Tony Automotive Pte Ltd

8 Kaki Bukit Ave 4 #04-07 Premier @ KB Singapore 415875

Tel: 69763261 Fax: 69763271

Email: tony07auto@gmail.com

Co. Reg No.: 201939168R

*Not Authorized
Main
1/9/20
4/5 @ 7000/
take photo after repair
7 days*

ESTIMATE

Model : **Mazda CX3**

Veh No: **SMM48325**

Qty	List Items	Amount S\$
1	REAR BUMPER	Dis 1088.4 ✓
2	SENSOR, ULTRASONIC CENTER	Dis 135.8 ✓
1	RETAINER LHS, SENSOR	Set 19.4 ✓
2	SENSOR, ULTRASONIC SIDE	Suc 132.3 X
1	RETAINER RHS, SENSOR	11 19.4 X
1	REAR BUMPER UNDER COVER	11 42.6 X
2	REAR BUMPER SIDE BRACKETS LHS RHS @ 64.40	Set 128.8 ✓
1	REAR BUMPER CENTER BRACKET	cm 26.1 ✓
1	REAR BUMPER REFLECTOR RHS	cm 84.9 ✓
1	REAR BUMPER REFLECTOR LHS	cm 84.9 ✓
1	REAR BUMPER REINFORCEMENT	Dis 432 ✓
1	REAR BUMPER REINFORCEMENT BRACKET LHS	NS 32.8 X
1	REAR BUMPER REINFORCEMENT BRACKET RHS	NS 32.8 X
1	REAR BUMPER TOW HOOK COVER	NF 18 X
1	BOOT LID	Body 1089.9 ✓
1	BOOT LID INNER GARNISH	11 233.2 ✓
1	BOOT LID LOCK	shiled 213.4 ✓
1	BOOT LID LOCK STRIKER	11 36 X
1	BOOT LID WEATHERSTRIP	11 167 ✓
1	Rear floor panel top board 478.80	11 606.4 ✓
1	BOOT LID END GARNISH CENTER	NS 232 X
1	BOOT LID END HANDLE	11 38 X
1	REAR TAIL LAMP RHS	scat/cr 772.3 ✓
1	REAR TAIL LAMP BRACKET RHS	11 36.2 X
1	REAR TAIL LAMP LHS	scat/cr 772.3 ✓
1	REAR TAIL LAMP BRACKET LHS	11 36.2 X
1	REAR EXHAUST MOUNTING	11 31.8 X
1	REAR EXHAUST GASKET	11 48.2 X
1	REAR EXHAUST	11 1670.4 X
1	REAR EXHAUST heat shield 266.80	Dis 1829.2 ✓
1	BOOT LID LOGO	11 55.5 ✓
1	BOOT LID EMBLEM - CX-3	11 56.5 ✓
1	BOOT LID EMBLEM - SKYACTIV	11 59.5 ✓
1	REAR FENDER RHS	11 1083.2 X
1	REAR FENDER LHS	11 1083.2 X
1	REAR END PANEL	Body 485.5 ✓
1	REAR END PANEL TOP GARNISH	11 88.7 ✓
1	SPARE WHEEL PANEL	crumpled/suc 722.7 ✓



Tony Automotive Pte Ltd

8 Kaki Bukit Ave 4 #04-07 Premier @ KB Singapore 415875

Tel: 69763261 Fax: 69763271

Email: tony07auto@gmail.com

Co. Reg No.: 201939168R

ESTIMATE

Model : **Mazda CX3**

Veh No: **SMM4832S**

Parts	Sub Total	13725.5
	Less 20%	2745.10
		<u>10980.40</u>

Special Nett Items

Qty	List Items
1 SET	REAR NUMBER PLATE AND HOLDER
1 SET	REAR BUMPER CLIPS
1 SET	TAIL LAMP CLIP SET
1	Rear Windscreen SEALANT

	Amount S\$
3 set	40 ✓
RM	60 50
11	60 X
RM	30 ✓
Sub Total	<u>190</u>

Qty	Labour charges
1	TUFFKOTE
1	REMOVING AND REFITTING REAR BOOTLID WINDSHIELD
1	TO PUTTY, SPRAY PAINT ETC
1	TO PANEL BEAT, WELD, ALIGN ETC

100	90
300	120
1500	1200
2000	1300
Sub Total	<u>3900</u>

ESTIMATE PARTS AND LABOUR GRAND TOTAL S\$ \$15,070.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7462-4
201
P-596992
S.W.-120-25
L-2710-22
879992
201
7039