

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)
8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875
Tel : 6341 6789 Fax: 6341 6778
E-mail:visionautowork@gmail.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

DATE : 31.08.20

Acknowledged by Repairer

Signature:

Date:

TO : NTUC MOTOR CLAIMS DEPTS
VEHICLE NO : YQ2412X
MODEL : MIT-FUSO FK62FMA40195
DATE OF ACCIDENT : 24.08.20
TIME OF ACCIDENT : 16:00HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL S/NETT
1	REAR SIDE PANEL RH <i>Dented.</i>	1	\$ 3,800.00	\$ 3,800.00
2	REAR SIDE PANEL LOWER PROTECTOR RH <i>Dented</i>	1	\$ 1,200.00	\$ 1,200.00
3	REAR SIDE PANEL INNER PILLAR <i>Repair</i>	1	\$ 1,200.00	\$ 1,200.00
4	REAR SIDE PANEL INNER PANEL (WOODEN) <i>rip in</i>	1	\$ 480.00	\$ 480.00
5	REAR SIDE PANEL INNER LOWER SUPPORT <i>Dented</i>	1	\$ 800.00	\$ 800.00
6	SIDE END PANEL RH <i>Repair</i>	1	\$ 2,800.00	\$ 2,800.00
7	REAR BOX FLOOR PANEL (WOODEN) <i>rip in</i>	2	\$ 1,800.00	\$ 3,600.00
8	REAR BOX CHASSIS MEMBER SUPPORT <i>Crushed</i>	3	\$ 1,400.00	\$ 4,200.00
9	COMPANY STICKER (SET) <i>NEW</i>	1	\$ 4,800.00	\$ 4,800.00

Fully painted (1 piece)

TOTAL \$ 18,080.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 1,600.00	600.
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,600.00	400.
3	WIRING, BULB CHECKING	\$ 80.00	x.

TOTAL \$ 3,280.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 18,080.00
TOTAL LABOUR COST : \$ 3,280.00
TOTAL REPAIR COST : \$ 21,360.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

Adnan
1/2 01/09/20

6 to 7 days
07.

total: 6500

1/5: 5.21c