

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

01/09/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP AXA.

Cecilia.

Accident date: 31/08/2020

Estimated repair cost for vehicle no: GBC6714U TOYOTA HIACE MANUAL13'

CHASSIS: JTFHT02P000115645

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Detent</i>		\$1,712.45 ✓
2	2	Rear Boot Lid Hinge <i>3 new</i>	\$171.70	\$343.40 x
3	2	Rear Boot Lid Shock Absorber <i>3 new</i>	\$281.90	\$563.80 +
4	1	Rear Boot Lid Emblem Logo <i>3 new</i>		\$51.10 ✓
5	1	Rear Boot Lid 70km/H Sticker		\$30.00 -15 (sw)
6	1	Rear Boot Lid Hiace Sticker		\$35.75 ✓
7	1	Rear Boot Lid Advertistment Sticker (Special Nett) <i>new</i>		\$2,000.00 -600 (sw)
8	1	Rear Boot Lid Centre Moulding <i>Detent</i>		\$261.60 ✓
9	1	Rear Boot Lid Number Plate <i>Detent</i>		\$50.00 -50 (sw)
10	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$83.10	\$166.20 +
11	1	Rear Boot Lid Inner Lock <i>Detent</i>		\$374.25 ✓
12	1	Rear Boot Lid Inner Lock Cover <i>Not new</i>		\$162.00 x
13	1	Rear Boot Lid Inner Power Lock Motor <i>Detent</i>		\$581.45 -245.
14	1	Rear Boot Lid Inner Rubber <i>Detent</i>		\$281.35 ✓
15	1	Rear Boot Lid Inner Trim Board <i>3 new</i>		\$372.25 x
16	10	Rear Boot Lid Inner Trim Board Clip <i>3 new</i>	\$6.50	\$65.00 x.
17	1	Rear Boot Lid Windscreen <i>new</i>		\$1,217.10 +
18	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$105.00 ✓
19	1	Rear Boot Lid Windscreen Number Sticker		\$200.00 x.
20	2	Rear Tail Lamp <i>Detent</i>	\$374.45	\$748.90 ✓
21	2	Rear Tail Lamp Lower Cover <i>RH Detent</i>	\$182.10	\$364.20 -182.10
22	2	Rear Tail Lamp Lower Cover Retainer <i>new</i>	\$171.45	\$342.90 x.
23	1	Rear Bumper <i>Detent</i>		\$374.40 ✓
24	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 -30
25	2	Rear Bumper Side Retainer <i>new</i>	\$121.25	\$242.50 ✓
26	1	Rear Bumper Centre Step Panel <i>new</i>		\$271.85 +
27	1	Rear End Panel Outer <i>Detent</i>		\$591.60 ✓

28	1	Rear End Panel Inner	Dented		\$781.90	✓
29	1	Rear Floor Panel	Repair		\$1,972.85	+
30	1	Rear Floor Panel Top Moulding	Bent		\$274.45	✓
31	8	Rear Floor Panel Top Moulding Clip	new	\$6.50	\$52.00	20
32	1	Rear Floor Panel Plywood	new		\$650.00	+
33	1	Rear Floor Panel Carpet	new		\$850.00	+
34	1	Rear Spare Tyre Bracket	new		\$243.10	+
35	1	Rear Exhaust	2		\$1,712.65	+
36	2	Rear Exhaust Mounting	new	\$61.75	\$123.50	+
37	1	Rear Centre Exhaust	new		\$1,829.10	+

Subtotal:- \$20,063.60

6312.35 S.N: 645.
4734.26

Labour charges

To remove & refit rear windscreen	\$120.00	✓
Gum	\$50.00	✓
To remove & refit rear & centre exhaust	\$380.00	+
To remove & refit carpet & plywood	\$280.00	80
To check wiring	\$100.00	30
Towing fee	2140 \$100.00	+
Tuff kote	\$150.00	60
Panel beating	\$1,200.00	1200
Spray painting	\$1,200.00	800
Subtotal:-	\$3,580.00	

Adrian L
Total:- \$23,643.60

H/S 02/09/20

total: 7519.26

c/s: 6K

(610)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7 DAYS