



# ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921  
 Tel: +65 67412845 Fax No: +65 67412170  
 Email: zero\_gravity@singnet.com.sg  
 Reg.No.: 52888887X

## QUOTATION

No : QT-000224

NTUC INCOME INSURANCE COOPERATIVE LIMITED

75 BRAS BASAH ROAD

NTUC INCOME CENTRE

SINGAPORE 189557

Attention: Motor Claim Department

TEL : 63462663

FAX : 63381500

Your Ref. : SJN3810S  
 Vehicle No. : SCJ290R  
 Make & Model : BMW 523I  
 Chassis No. : WBAFP32000C864031  
 Engine No. : 08787680N52B25AF  
 Accident Date : 29/08/2020  
 Policy No. : B300272470SMP  
 Date : 31/08/2020  
 Page : 1 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
1	FRONT BUMPER / DEF	1.0	PCS 1,265.00	1,265.00 /
2	FRONT BUMPER SPONGE (CENTER) ? / BR	1.0	PCS 60.50	60.50 /
3	FRONT BUMPER REINFORCEMENT ? X NM	1.0	PCS 682.00	682.00 X
4	FRONT GRILLE / CUT	2.0	PCS 146.30	292.60 /
5	FRONT GRILLE (INNER GARNISH) ? / BR	2.0	PCS 396.00	792.00 /
6	BUMPER BEAM SCREW/INNER CLIPS SET ? / APC	2.0	SET 80.00	50 / 160.00
7	FRONT BUMPER GRILLE (BOTTOM) X NM	1.0	PCS 75.80	75.80 X
8	FRONT BUMPER GRILLE (BOTTOM AIR GARNISH) X NM	1.0	PCS 148.00	148.00 X
9	SENSOR (FRONT BUMPER) (CENTER) / (short)	1.20	PCS 329.00	658.00 /
10	HEADLIGHT (L/H) / BR	1.0	PCS 1,375.00	1,375.00 /
11	HEADLIGHT CONTROL UNIT (L/H/F) X NM	1.0	PCS 840.00	840.00 X
12	HEADLIGHT (TOP RUBBER) X NM	2.0	PCS 36.30	72.60 X
13	HEADLIGHT LOWER BRACKET (L/H) ? X NM	1.0	PCS 154.00	154.00 X
14	REAR BUMPER / BR	1.0	PCS 1,560.50	1,560.50 /
15	REAR BUMPER REINFORCEMENT ? / OD	1.0	PCS 421.20	421.20 /
16	BUMPER HOOK COVER / MIS	1.0	PCS 19.60	19.60 /
17	REAR BUMPER REFLECTOR (L/H) ? / BR	1.0	PCS 21.00	21.00 /
18	REAR BUMPER REFLECTOR (R/H) X NM	1.0	PCS 21.00	21.00 X
19	BUMPER SIDE RETAINER (L/H/R) / BR	1.0	PCS 151.40	151.40 /
20	BUMPER SIDE RETAINER (R/H/R) / BR	1.0	PCS 151.40	151.40 /
21	REAR BUMPER TOP RETAINER ? / BR	1.0	PCS 84.00	84.00 /
22	REVERSE SENSOR / (short)	3.0	SET 291.70	875.10 /
23	REAR BOOT / OD	1.0	PCS 1,700.00	1,700.00 /
24	REAR BOOT STOPPER BUSH X NM	2.0	PCS 22.00	44.00 X
25	LOGO / MK	1.0	PCS 64.00	64.00 /
26	EMBLEM "523I" / MK	1.0	PCS 88.00	88.00 /



# ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921  
 Tel: +65 67412845 Fax No: +65 67412170  
 Email: zero\_gravity@singnet.com.sg  
 Reg.No.: 52888887X

## QUOTATION

No : QT-000224

NTUC INCOME INSURANCE COOPERATIVE LIMITED

75 BRAS BASAH ROAD

NTUC INCOME CENTRE  
 SINGAPORE 189557

Attention: Motor Claim Department

TEL : 63462663

FAX : 63381500

Your Ref. : SJN3810S  
 Vehicle No. : SCJ290R  
 Make & Model : BMW 523I  
 Chasis No. : WBAFP32000C864031  
 Engine No. : 08787680N52B25AF  
 Accident Date : 29/08/2020  
 Policy No. : B300272470SMP  
 Date : 31/08/2020  
 Page : 2 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
27	LAMP (L/H/R) (LH) ? X NM	1.0	PCS 630.00	630.00 X
28	LAMP (R/H/R) X NM	1.0	PCS 630.00	630.00 X
29	LAMP (REAR) X NM	2.0	PCS 560.00	1,120.00 X
30	REAR END PANEL ? / DD	1.0	PCS 619.00	619.00 /
31	REAR END PANEL GARNISH ? X NM	1.0	PCS 59.00	59.00 X
32	REAR BOOT WEATHERSTRIP ? / TM	1.0	PCS 97.00	97.00 /
33	REAR BOOT INNER LOCK / BT	1.0	PCS 199.00	199.00 /
34	SUPPORTS / NK	1.0	SET 30 / 120.00	120.00 /
35	AIR BAG (HEAD RESTRAINT) / Damaged	2.0	PCS 305.00	610.00 /
36	CONTROL UNIT (AIR BAG) X NM	1.0	PCS 1,245.60	1,245.60 X
37	EXHAUST TAIL PIPE (CHROME) / CUT	2.0	PCS 220.00	440.00 /
38	EXHAUST MUFFLER X NM	1.0	PCS 1,625.00	1,625.00 X
39	REAR BOTTOM DEFUSER (UNDER COVER) ? / BR	1.0	PCS 293.10	293.10 /
40	Discount 5 %			-973.22
41	SubTotal (L)			18,491.18
42	FRONT NUMBER PLATE / CUT	1.0	PCS 35.00	35.00 /
43	REAR NUMBER PLATE CUT /	1.0	PCS 35.00	35.00 /
44	REAR END PANEL SEALANT ? / NK	1.0	BTL 50.00 30 /	50.00 /
45	SubTotal (S)			120.00
46	PANEL BEAT & REPAIR FRONT DAMAGE	1.0	X 300	500.00
47	PANEL BEAT & REPAIR REAR DAMAGE	1.0	X 600	1,000.00
48	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0	X 900	1,200.00
49	TO PROVIDE UNDER TURF COAT	1.0	X 50	280.00
50	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1.0	X 30	80.00
51	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0	X 80	250.00
52	TO REMOVE BUMPER / REVERSE SENSOR	1.0	X 30	150.00



# ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero\_gravity@singnet.com.sg

Reg.No.: 52888887X

## QUOTATION

No : QT-000224

NTUC INCOME INSURANCE COOPERATIVE LIMITED

Your Ref. : SJN38105  
 Vehicle No. : SCJ290R  
 Make & Model : BMW 523i  
 Chasis No. : WBAFP32000C864031  
 Engine No. : 08787680N52B25AF  
 Accident Date : 29/08/2020  
 Policy No. : B300272470SMP  
 Date : 31/08/2020  
 Page : 3 of 3

75 BRAS BASAH ROAD

NTUC INCOME CENTRE

SINGAPORE 189557

Attention: Motor Claim Department

TEL : 63462663

FAX : 63381500

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
53	TO TRANSFER REAR BOOT FITTING	1.0 X	50	180.00
54	CONTROL UNIT ADAPTATION AND REPROGRAMMING (AIR BAG)	1.0 X	150	350.00
55	TO REMOVE AND REPLACE DAMAGED EXHAUST SYSTEM	1.0 X	50	120.00
56	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1.0 X	2360 X	80.00
57	SubTotal (LABOUR)			4,190.00

Steve (LKK)  
 8322 8813

WHL P/L  
 11/9/20, 11.9000

98 days

L/S

By AL SM

P- 10,429.56

L- 2360

SUPP- 1666.08

14,455.64

L/S - 11,564.51

= 11,550.99

Repair limit \$7000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to approval from Insurance Company

ACKNOWLEDGED BY REPAIRER  
 Signature & O.E.  
 Date:

TWO THOUSAND EIGHT HUNDRED ONE AND CENTS

Total	S\$	22,801.18
Discount	S\$	0.00
Net Total	S\$	22,801.18

Terms: C.O.D.

Customer's Signature/Co. Stamp

ZERO GRAVITY

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.



# ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921  
 Tel: +65 67412845 Fax No: +65 67412170  
 Email: zero\_gravity@singnet.com.sg  
 Reg.No.: 52888887X

## QUOTATION

No : QT-000225

NTUC INCOME INSURANCE COOPERATIVE LIMITED

75 BRAS BASAH ROAD  
 NTUC INCOME CENTRE  
 SINGAPORE 189557

Attention: Motor Claim Department

TEL : 63462663

FAX : 63381500

2/9/20  
 Steve (LKK)

Your Ref. : SJN38105  
 Vehicle No. : SCJ290R  
 Make & Model : BMW 523I  
 Chasis No. : WBAFP32000C864031  
 Engine No. : 08787680N52B25AF  
 Accident Date : 29/08/2020  
 Policy No. : B300272470SMP  
 Date : 01/09/2020  
 Page : 1 of 1

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
1	CONTROL UNIT (HANDBRAKE) ✓ BR	1.0	585.00	585.00 ✓
2	SENSOR (KEY) X NM	1.0	185.00	185.00 X
3	GARNISH (LAMP) (L/H/R) (LH) ✓ TM	1.0	52.00	52.00 ✓
4	BUMPER BEAM RETAINER LOWER (REAR) ✓ BR	1.0	175.00	175.00 ✓
5	FOG LIGHT GARNISH (L/H) ✓ BR	1.0	308.00	308.00 ✓
6	SUPPORT PANEL GARNISH (CENTER) ✓ BR	1.0	270.00	270.00 ✓
7	SUPPORT PANEL GARNISH (LOWER GRILLE) (L/H) X NM	1.0	66.00	66.00 X
8	SUPPORT PANEL GARNISH (CENTER/INNER) ✓ BR	1.0	461.20	461.20 ✓
9	Discount 5 %			-105.11
10	SubTotal (L)			1,997.09
11	REMARKS: SUPPLEMENTARY ESTIMATE			

1851.20  
 -19%  
 1666.98

SINGAPORE DOLLAR ONE THOUSAND NINE HUNDRED NINETY SEVEN AND CENTS NINE ONLY

E. & O.E

Total	S\$	1,997.09
Discount	S\$	0.00
Net Total	S\$	1,997.09

Terms: C.O.D.

Customer's Signature/Co. Stamp

ZERO GRAVITY

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise if is assumed that this bill is accepted as correct.