



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20009263/DUqf3q2	
			Date: 16/03/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBA 9656U	Veh. Inspected	SGU 2222U	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2002550/IJH	Excess (\$)	0.00	
Assign From	IRENE HENRY	Assign Date	01/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALPHARD	c.c	2494	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	AGH300058482	Colour	WHITE	
Odometer	78801 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R20	MICHELIN	5 mm	
L/H Front Tyre	245/40 R20	MICHELIN	5 mm	
R/H Rear Tyre	245/40 R20	MICHELIN	5 mm	
L/H Rear Tyre	245/40 R20	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/08/2020	Inspection Date	01/09/2020	
Survey held at	53 UBI AVENUE 1,#01-16 PAYA UBI IND.PARK			
Repairer	TEAMWORK GARAGE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	