

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CC3/TP20009272/Kda3q2	
NO.2 ANG MO KIO ST	REET 63SINGAPORE 569111	Date: 20-11-2020 Code: TP378	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.		Veh. Inspected	SHC 5311J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	31/08/2020
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JTDKB3FU303091200	Colour	M.P WHITE / RED
Odometer	12533	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	DUNLOP	9 mm
L/H Front Tyre	195/65 R15	DUNLOP	9 mm
R/H Rear Tyre	195/65 R15	DUNLOP	9 mm
L/H Rear Tyre	195/65 R15	DUNLOP	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/08/2020	Inspection Date	31/08/2020
Survey held at	TRANS-CAB AUTO SERVICES	PTE LTD	
	NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days			