

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 47453

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0616/2020/NS
Date : 31-Aug-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Guo Qiang,
5 days - ok - Jy - 22 Oct 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Chee Hwei Leng
Address : 7 Butterfly Avenue
Singapore 349762
Telephone : HP +65 81252678
Type of Claim : Own Damage Claims
Policy No. : 1900005737-01
Vehicle No : **EV 96 Z**
Model Code : Audi A4 Sedan 2.0 TFSI 8W
Model / Year : Jan-19
Engine No : CVK 072228
Chassis No : WAUZZZF44KN000873
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Aug-20
Place of Accident : Grange Road Near One Twin Peaks Condominium

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle EV 96 Z

S/N	Nature of Jobs			Estimated Charges		Surveyor's Recommendations
1	To remove, check and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$	280.00	\$	280.00
2	To remove and transfer both headlight control units and power modules.	S/N	\$	700.00	\$	350.00
3	To remove and renew aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$	1,200.00		
4	To dismantle and renew front bumper, bonnet, and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.		\$	4,200.00	\$	1,000.00
5	To respray front bumper, bonnet and hinges.		\$	2,500.00	\$	1,100.00
6	Supplementary		\$	480.00	\$	480.00
7	To carry out diagnostic check.	S/N	\$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$	9,552.00	\$	3,402.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EV 96 Z

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,171.00	\$ 1,736.80
2	FRONT BUMPER FIXING PARTS	\$ 580.00	
3	FRONT BUMPER SECURING STRIP	2 \$ 70.00	
4	FRONT BUMPER GRILLE - CENTRE	\$ 194.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 208.00	
6	RADIATOR GRILLE	\$ 1,317.00	\$ 1,053.60
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 268.00	
8	FRONT BUMPER CARRIER	\$ 795.00	\$ 635.60
9	FRONT BUMPER FOAM FILLER PIECE	\$ 123.00	\$ 98.40
10	FRONT BUMPER BRACKET - LH / RH	2 \$ 450.00	
11	FRONT BUMPER COVER	\$ 126.00	\$ 100.40
12	CAUTION SIGN STICKER	NEC \$ 14.00	\$ 10.80
13	AIRCON STICKER	NEC \$ 8.00	\$ 5.68
14	LOCK CARRIER BRACKET	\$ 136.00	\$ 108.40
15	FRONT BUMPER SUPPORT - LH / RH	2 \$ 56.00	\$ 44.48
16	FRONT PARKING AID SENSOR - INNER / OUTER	2 TBC	
17	HORN - LH HIGH TONE	\$ 124.00	
18	HORN - RH LOW TONE	\$ 124.00	
19	SPRING SHACKLE - LH / RH	2 \$ 58.00	
20	BONNET	\$ 2,763.00	
SUB TOTAL SPARE PARTS CHARGES		: \$ 9,585.00	\$ 3,794.16

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EV 96 Z

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
		<i>c/f</i>		\$ 3,794.16
21	BONNET ATTACHMENT PARTS		\$ 408.00	
22	BONNET LID HINGE - LH / RH	2	\$ 602.00	
23	BONNET IMPACT PROTECTION - CENTRE		\$ 27.00	\$ 21.52
24	BONNET IMPACT PROTECTION - LH		\$ 28.00	\$ 21.84
25	BONNET IMPACT PROTECTION - RH		\$ 27.00	\$ 21.52
26	BONNET STRIKER - LH / RH	2	\$ 100.00	
27	BONNET LID LOCK	2	\$ 423.00	
28	BONNET BOWDEN CABLE		\$ 57.00	
29	BONNET RELEASE LEVER		\$ 13.00	
30	LED HEADLIGHT - LH / RH	2	\$ 15,386.00	\$ 6,154.40
31	LIFT CYLINDER - LH / RH	2	\$ 416.00	
32	LIFT CYLINDER CORRUGATED PIPE		\$ 92.00	
33	LOCK CARRIER		\$ 1,004.00	
34	COOLANT REGULATOR SUPPORT	2	\$ 75.00	
35	READY MIX COOLANT		\$ 177.00	
36	AIRCON CONDENSER		\$ 615.00	\$ 492.00
37	TEMPERATURE SENSOR BRACKET		\$ 18.00	\$ 14.40
38	RADIATOR AIR GUIDE - LH / RH	2	\$ 56.00	
39	RADIATOR AIR GUIDE - LH / RH	2	\$ 24.00	\$ 18.72
40	RADIATOR AIR GUIDE - UPPER		\$ 16.00	
41	RADIATOR AIR GUIDE - LOWER		\$ 22.00	
42	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
44	SUNDRIES		\$ 350.00	\$ 2.24
TOTAL SPARE PARTS CHARGES			\$ 29,581.00	\$ 10,600.80
TOTAL LABOUR CHARGES			\$ 9,552.00	\$ 3,402.00
GRAND TOTAL			\$ 39,133.00	\$ 14,002.80

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0616/2020/NS Glory Tan 1 OF 1 EV 96 Z Audi A4 Sedan 2.0 TFSI 8W	
Quantity	Description		Unit Price	Amount
<u>Labours</u>				
1	To remove and renew aircon condenser. To pressurise cooling system, vaccum and regas.	s/n	\$ 480.00	\$ 480.00
TOTAL			\$ 480.00	\$ 480.00

For Premium Automobiles Pte Ltd

 Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant