

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 47453

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0616/2020/NS
Date : 31-Aug-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Chee Huei Leng
Address : 7 Butterfly Avenue
Singapore 349762
Telephone : HP +65 81252678
Type of Claim : Own Damage Claims
Policy No. : 1900005737-01
Vehicle No : **EV 96 Z**
Model Code : Audi A4 Sedan 2.0 TFSI 8W
Model / Year : Jan-19
Engine No : CVK 072228
Chassis No : WAUZZZF44KN000873
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Aug-20
Place of Accident : Grange Road Near One Twin Peaks Condominium

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle EV 96 Z

S/N	Nature of jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 280.00	✓
2	To remove and transfer both headlight control units and power modules.	S/N \$ 700.00	417 LH ✓ 350 250 ✓
3	To remove and renew aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	X NN 750 ✓
4	To dismantle and renew front bumper, bonnet, and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 4,200.00	1000 500 950
5	To respray front bumper, bonnet and hinges.	\$ 2,500.00	1100 ✓
6	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 9,072.00	2572 3052

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EV 96 Z

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER / <i>le</i>	\$ 2,171.00	1736.8
2	FRONT BUMPER FIXING PARTS / <i>MC L</i>	\$ 580.00	X NN
3	FRONT BUMPER SECURING STRIP <i>X</i> NN	2 \$ 70.00	
4	FRONT BUMPER GRILLE - CENTRE <i>X NN</i>	\$ 194.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>X</i> NN	\$ 208.00	
6	RADIATOR GRILLE / <i>CR A</i>	\$ 1,317.00	1053.6
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>LH X NN</i>	\$ 268.00	
8	FRONT BUMPER CARRIER / <i>BT (photo)</i> <i>RH X NN²</i>	\$ 795.00	635.6
9	FRONT BUMPER FOAM FILLER PIECE <i>CR A (photo)</i>	\$ 123.00	98.4
10	FRONT BUMPER BRACKET - LH / RH <i>X</i> NN	2 \$ 450.00	
11	FRONT BUMPER COVER <i>X</i> BR	\$ 126.00	100.4
12	CAUTION SIGN STICKER <i>X</i> NEC	NEC \$ 14.00	10.8
13	AIRCON STICKER <i>X</i> NEC	NEC \$ 8.00	5.68
14	LOCK CARRIER BRACKET <i>X</i> BR	\$ 136.00	108.4
15	FRONT BUMPER SUPPORT - LH / RH <i>X</i> BR	2 \$ 56.00	44.48
16	FRONT PARKING AID SENSOR - INNER / OUTER <i>X</i>	2 TBC	
17	HORN - LH HIGH TONE <i>X</i>	\$ 124.00	
18	HORN - RH LOW TONE <i>X</i>	\$ 124.00	
19	SPRING SHACKLE - LH / RH <i>X</i>	2 \$ 58.00	
20	BONNET <i>Repair X</i>	\$ 2,763.00	
SUB TOTAL SPARE PARTS CHARGES		: <u>\$ 9,585.00</u>	3794.16

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EV 96 Z

S/N	Parts Description	Damage Parts & Prices		
		S/Nett	Remarks	
21	BONNET ATTACHMENT PARTS X	\$	408.00	
22	BONNET LID HINGE - LH / RH X	2 \$	602.00	
23	BONNET IMPACT PROTECTION - CENTRE	\$	27.00	21.52
24	BONNET IMPACT PROTECTION - LH	\$	28.00	21.84
25	BONNET IMPACT PROTECTION - RH	\$	27.00	21.52
26	BONNET STRIKER - LH / RH X	2 \$	100.00	
27	BONNET LID LOCK X	2 \$	423.00	
28	BONNET BOWDEN CABLE X	\$	57.00	
29	BONNET RELEASE LEVER X	\$	13.00	
30	LED HEADLIGHT - LH / RH X	2 \$	15,386.00	6154.4
31	LIFT CYLINDER - LH / RH X	2 \$	416.00	
32	LIFT CYLINDER CORRUGATED PIPE X	\$	92.00	
33	LOCK CARRIER X	\$	1,004.00	
34	COOLANT REGULATOR SUPPORT X	2 \$	75.00	
35	READY MIX COOLANT X	\$	177.00	
36	AIRCON CONDENSER X ✓ BT	\$	615.00	492
37	TEMPERATURE SENSOR BRACKET X ✓ BR	\$	18.00	14.4
38	RADIATOR AIR GUIDE - LH / RH X NN	2 \$	56.00	
39	RADIATOR AIR GUIDE - LH / RH X BR	2 \$	24.00	18.72
40	RADIATOR AIR GUIDE - UPPER X NN	\$	16.00	
41	RADIATOR AIR GUIDE - LOWER X NN	\$	22.00	
42	FRONT NO PLATE ✓ BT	S/N \$	60.00	✓
43	SUNDRIES ✓ NEC	\$	350.00	2.24
TOTAL SPARE PARTS CHARGES		:	\$ 29,581.00	6806.64
TOTAL LABOUR CHARGES		:	\$ 9,072.00	10600.8
GRAND TOTAL		:	\$ 38,653.00	3052
				13652.8

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Ano Qiam - 82880282
: Not Authorised.
: before paint photos.
: 01/9/2020.
: 5 Days.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant