

Our Job Ref No 305419359

Date : 01.09.20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr TAUFIKH

Vehicle Reg No. SHA1206S CTPL

28.08.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- GBK3808K

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

20%

\$750.00

Final Lumpsum Repair cost**\$750.00**

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : _____

Name : _____

Date : _____

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305419359
 REGN NO : SHA1206S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 10.08.2018
 DATE/TIME IN : 29.08.2020 08:50
 ACCIDENT DATE : 28.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER	1 L	459.40 20.00 367.52 Ryo
0002	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00 20.00 17.60 X
0003	04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1 L	451.25 20.00 361.00 de
0004	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	180.00 10.00 162.00 ?

SUB-TOTAL : 908.12

451.25
 -20%
 361.00

JOB NATURE

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000	L	PANEL BEATING	350.00	320
0001	23-502	SPRAYPAINT ON AFFECTED AREA	250.00	200
0002	20-22	REMOVE/REFIX REVERSE SENSOR	80.00	30

SUB-TOTAL : 680.00

550
 911.00
 -20%
 728.80

TOTAL : 1,588.12

MVA NAME & SIGNATURE
 DATE :

SURVEYOR NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO

Tanpin 97415746 Davanti
 up 31/8/20 @ 3pm

2 days
 4/5 Resuming after repair \$750/-
 Tanpin C. Khantawon