

LKe

NTUC

COMFORTDELGRO ENGINEERING PTE LTD

Date: 29.08.2020

REPAIR ESTIMATE

Time: 11:37:24

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305419359
REGN NO : SHA1206S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 10.08.2018
DATE/TIME IN : 29.08.2020 08:50
ACCIDENT DATE : 28.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER	1 L	459.40	20.00	367.52	<i>Ry</i>
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	<i>Xnn</i>
0003 04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1 L	451.25	20.00	361.00	<i>de</i>
0004 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	180.00	10.00	162.00	<i>Xnn 361</i>
SUB-TOTAL :						908.12

JOB NATURE

0000 L	PANEL BEATING	350.00	<i>320</i>
0001 23-502	SPRAYPAINT ON AFFECTED AREA	250.00	<i>200</i>
0002 20-22	REMOVE/REFIX REVERSE SENSOR	80.00	<i>30 550</i>
SUB-TOTAL :		680.00	

TOTAL : 1,588.12

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

Tanpin 97415744 Davanti
wp 31/8/20 @ 3pm
2 days
4/5 Resurvey after repair
Tanpin C Khantawon

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4911
23/8
4/5 \$750 #
2 days