

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

idac

Page No.:1 of 2

Reg. No: 52983356E GST Reg. No. 20-0405911-H

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8182U

| Qty | Description of Parts                                      | Condition               | Estimate By<br>Workshop (\$) | Our Adjusted<br>(\$) |
|-----|---|-------------------------|------------------------------|----------------------|
|     | REPLACEMENT OF PARTS                                      |                         |                              |                      |
| 1   | FRT DOOR LH   | BENT                    | 2,256.40                     | 2,256.40             |
| 1   | REAR DOOR LH  | BENT                    | 2,201.10                     | 2,201.10             |
| 1   | WING MIRROR LH  | TO REPAIR SEE<br>LABOUR | 670.00                       | -                    |
| 1   | ROCKER PANEL GARNISH LH                                   | DISTORTED               | 403.00                       | 403.00               |
|     | LESS 20% DISCOUNT   |                         | -1,106.10                    | -972.10              |
|     |   |                         | 4,424.40                     | 3,888.40             |
|     | NETT ITEMS  |                         |                              |                      |
| 1   | FRT DOOR COMFORTDELGRO LH (N)                             | NECESSARY               | 75.00                        | 75.00                |
| 1   | REAR DOOR APPS LH (N)                                     | NECESSARY               | 80.00                        | 80.00                |
|     | LESS 10% DISCOUNT   |                         | -15.50                       | -15.50               |
|     |   |                         | 139.50                       | 139.50               |
|     | SPECIAL NETT ITEMS  |                         |                              |                      |
| 1   | FRT DOOR ADV. STICKER LH (SN)                             | NECESSARY               | 100.00                       | 100.00               |
| 1   | REAR DOOR ADV. STICKER LH (SN)                            | NECESSARY               | 100.00                       | 100.00               |
|     |   |                         | 200.00                       | 200.00               |
|     | <u>LABOUR</u>   |                         |                              |                      |
|     | PANEL BEATING. INCLUSIVE OF THE REPAIR OF WING MIRROR LH. |                         | 300.00                       | 280.00               |
|     | SPRAYPAINT CHARGE.  |                         | 600.00                       | 600.00               |
|     | TUFF COAT ON AFFECTED PARTS.                              |                         | 80.00                        | 40.00                |
|     | TRANSFER OF DOORS.  |                         | 120.00                       | 120.00               |
|     |   |                         | -                            | -                    |
|     |   |                         | -                            | -                    |
|     |   |                         | -                            | -                    |
|     |   |                         | 1,100.00                     | 1,040.00             |
|     | GRAND TOTAL   |                         | 5,863.90                     | 5,267.90             |





| RECOMMENDED COST OF LUMP SUM REPAIRS        | 4,200.00 |
|---|----------|
| (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) |          |

Report Ref No. NS/INC20009279/T1qf3e2

**MOHAMAD TAUFIKH** 

fourin.

M.MATAI, AMSAE-A

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser