

# COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

VEHICLE NO SHA7981Y

28.08.20

MAKE :

MODEL HYU-140

CHIANG/MSIC

NJMC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER REINFORCEMENT			\$428.40
1	REAR BUMPER UNDER COVER			\$228.00
1	BOOTLID 1-40 PLATE			\$27.90
1	BOOTLID CRDI PLATE			\$27.90
				\$1,911.40
	20.00% DISCOUNTED TOTAL		1356 1084.80	\$382.28 \$1,529.12
1	REVERSE SENSOR			\$135.70
1	BUMPER RUBBER MAT			\$50.00
1	BOOTID COMFORT LOGO STICKER			\$30.00
1	BOOTLID COMFORT TEL NO.			\$30.00
	BUMPER MAT		185.70	\$245.70
	Labour Charge			
	Panel Beating			\$540.00
	Spray Painting Charge			\$500.00
	Remove/refix reverse sensor		510	\$60.00
	Tuff Kote			\$90.00
	TOTAL LABOUR		1780.50	\$1,190.00
	ESTIMATE TOTAL		4/5 \$1400 2 days	\$2,964.82

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanjin 97445749  
wp  
31/8/20 3pm  
2 days  
4/5 Resurvey after repair  
Tanjin (handwritten)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: