

Our I	ob Ref	No 30	5419670			ENGINEERING
Date	ob Kei		Sep. 2020		Con	nfortDelGro Engineering Pte Ltd
	1747	-	вер. 2020		59 L	oyang Drive Singapore 508969 : 6546 8156
_	LIZATI	ON FORM				
То	: -		LKK		Fax:	
Attn	•		TAUFIKH			
Vehic	le Reg	No. : SHA	4762H	Dat	e of Accident:	27. Aug. 2020
The s	urvey a	and estimates of	the repairs of the a	bove-mentione	d vehicle are a	as follows:-
1.	The re	epair job shall bi	II to:	NTUC		SJD81B
2.	The fi	nalized amount	shall be:			
	(a)	Spare Parts aft	er List discount			×
	(b)	Labour Charge	s			
		Total for Part-l	By-Part Repair Co	st		
	(c.)		air (if applicable) sum repair cost afte n Repair cost	r Less:		\$1,650.00
			•			
	We sh within		s	rrect and Conf		is no reply from you estimates and
				fin	alized amount	
	Signat Name	ure :	TECK		gnature:	
	Tel	6214 831	6	Da	te :	
	Fax	6546 815	6	<del></del>		
For Of	ficial l	Jse Only				
	lt	tem	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rer	ntal Ra	te P/Day		YES		
2. Los	s of Inc	come Paid		NO		
3. Sur	vey Fe	es				
	Searching F		\$7.49			
5. Medical Fees (on behalf of driver, if applicable)						
Ove	rrun					
Remark	cs.					



VEHICLE NO. :	SHA4762H	TYPE OF CASE	:	NTUC
JOBCARD NO.	305419670	SURVEY BY	:	LKK- TAUFIKH
ACC.DATE	27.08.2020	DATE	:	

DESCRIPTION	QTY	ESTIMATE	REMARKS
Rear Fog Lamp	1	\$201.50	
Rear Bumper Reinforcement	1	\$294.80	
Antenna Assy-SMARTK	1	\$689.50	
Reverse sensor assy	1	\$180.00	
CUEOV ITEM			
CHECK ITEM			
LABOUR			
	TOTAL:	\$1,365.80	HONG