COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 31.03.2020

DATE:	31.03.3625		3P INSURANCE:	NTUC	-
ODEL:	HYUNDM CMO		SURVEYOR:	LKK	-
EH NO.:	SHA4762H		MVA:	Hong LT	-
WINO.	DESCRIPTION	QTY	LIST PRICE	REMARKS	
	Rear Bumper			\$459.40	de/
	Rear Bumper Centre Moulding Assy			¢151.25	111
	Rear Bumper Cover Clips			\$22.00	WCXNN
	Suff for fylong \$201.50. was New bunger bunfarenet \$294.80 cm Anterna 1825y-Smither \$189.50 and	ł			
	Antenna Masy-smaker disgaso and	/ 	1 1		2096.45
	SPARE PARTS SUB TOTAL			\$932.65	1677.16
	LESS 20%			\$186.53	
	DISCOUNTED SPARE PARTS TOTAL			\$746.12	
	Rear No. Plate <u>LKK Auto Consultants</u> hence notify		h l	\$25.00	Nett 04
	the Repairer of the following: • To resurvey before/after spray painting		180.	\$2.50	THE T
Sup	• To display damaged part(s) during resurv	ŧу		\$22.50	205
1	Parts prices are subject to confirmation Third party survey is on a "Without Prejudent	ica" basia			•
	No illegal modification(s) is allowed	ice basis			10%-184.50
	 Supplementary item(s) must be resurvey 				
	is subject to final approval from Insurance				
	Acknowledged by Repairer Signature: NETT TOTAL		ll t	£22.50	
	Signature:			\$22.50	
	DISCOUNTED SPARE PARTS & NETT TOTAL		┝┚	£750.00	
			†	\$768.62	
	Panel Beating			\$ 350.00	.20
	Spray Painting			\$250.00	200
	Remove/Refix Reverse Sensor			\$100.00	50
	Taylor 9249 5249 Daunch				, •
	WP 3//6/20 (3pm				550.
	-2 duy LABOUR TOTAL			\$700.00	•
	4/4 Resun after repor		l I		
	Tough 944545 Tough 944545 Paunit -2 duy LABOUR TOTAL LAGATE TOTAL Initial estimate based on a visual inspection of the above		[\$1,468.62	2411.60
his is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be repared after the vehicle is surveyed by a motor Surveyor appointed by the insurance quantum will be					1111-
repared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					2dys \$
					2 days \$