YCAB PTE LTD

EPAIR ESTIMATE*

SHC8854P VEHICLE NO

31/08/20

MAKE

TONIO 63

CHIANG / CHINA

MODEL	IONIQ GZ		CHIANG / CHINA	·	7
Qty	Parts Description/ Labour	Туре	Unit Price	Amount	0.0
Qiy	1 REAR BUMPER			\$459.40	NY
	1 REAR BUMPER BRACKET RH /LH			\$55.80	VIN.
	1REAR BUMPER CENTRE MOULDING			\$451.25	16/
1	1 REAR BUMPER TOW COVER			\$98.80	
<u> </u>	1REAR BUMPER REFLECTOR LH			\$31.90	Knn
	TREAK BOWN EN NET EECTON EN		11.26	\$1,097.15	-
	20.00%		1 451.25	\$219.43	
1	DISCOUNTED TOTAL		451.25 361	\$877.72	1
	DISCOUNTED TOTAL			-	1
					l
	1 REAR BUMPER MAT			\$50.00	xnn
l .	1 REAR REVERSE SENSOR			\$180.00	
	INCAN NEVERSE SENSON			V100.00	,
				\$230.00	
				\$250.00	
	Labour Charge				
	Panel Beating			\$700.00	320
	Spray Painting Charge		£10.	\$500.00	200
	Tuff Kote		520.	\$80.00	
	Remove/Refix reverse sensor			\$90.00	
	TOTAL LABOUR		4 0001	\$1,370.00	
	101/122/300/1		\$ 881	\$1,570.00	
	ESTIMATE TOTAL		2 days	\$2,477.72	
	ESTIMATE TOTAL)	\$2,477.72	
			*		
			7/1		
	This is an initial estimate based on a visual inspection of the	 !			
	Linis is an initial actimate hased on a visual inspection of the	20000000	viola. The final		

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tought 97495746) MIC W/ 31/8/30 C3pm 2 days P/ Reony after report fauftre literatoreser

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: