

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC8854P

31/08/20

MAKE :

MODEL IONIQ G2

CHIANG / CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$459.40
1	REAR BUMPER BRACKET RH /LH			\$55.80
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER TOW COVER			\$98.80
1	REAR BUMPER REFLECTOR LH			\$31.90
				\$1,097.15
				20.00% \$219.43
				DISCOUNTED TOTAL \$877.72
1	REAR BUMPER MAT			\$50.00
1	REAR REVERSE SENSOR			\$180.00
				\$230.00
	Labour Charge			
	Panel Beating			\$700.00
	Spray Painting Charge			\$500.00
	Tuff Kote			\$80.00
	Remove/Refix reverse sensor			\$90.00
				TOTAL LABOUR \$1,370.00
				ESTIMATE TOTAL \$2,477.72
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanphat 97495749 MLC
 WP 31/8/30 03pm
 2 days
 P/P Repair after repair
 tanphat@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 31.08.2020 13:00

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305419780

STOMER

V/MS COMFORT TRANSPORTATION PTE LTD

STOMER NO. 7010045

DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

SCOUNT CARD NO.

REGN NO:

SHC8854P

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN 31.08.2020 10:00

YR OF MANU.

18.03.2020

TARGET DATE

CHASSIS CODE

KMHC851CVLU190473

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 30.08.2020

NATURE: 3P 30.08.2020

S/NO

LABOR CODE

DESCRIPTION



ECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

Vehicle No.: SHC8854P CHIANG

Vehicle No.: SHC8854P

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard