

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 31391

Date : 01-Sep-2020

Vehicle Insured : SFK 933 D
Accident Date : 30-Aug-2020

Our Ref : 020405 (AIG ASIA) / QUEK

SHANEET NITYANAND RAI (MR)
Singapore

PAGE : 1

ESTIMATED COST OF REPAIR FOR LEXUS IS200T EXECUTIVE(1998cc)-2016 SLA2176R
=====

2 pcs rear number plate lamp assy (LH/RH)	@ S\$161.70	in 323.40	X
1 pc rear bumper - top	@ S\$145.00	in 290.00	X
2 pcs rear bumper side retainer (LH/RH)	@ S\$ 5.50	in 55.00	✓
10 pcs rear bumper clips		CM 503.30	✓
1 pc rear bumper - bottom	@ S\$167.80	in 335.60	X
2 pcs rear bumper reflector(LH/RH)	@ S\$490.80	in 1,963.20	?
24 pcs rear bumper parking sensor		CM 112.40	✓
1 pc rear bumper sponge		in 485.00	✓
1 pc rear bumper reinforcement		in 1,733.90	✓
1 pc bootlid	@ S\$223.70	in 447.40	X
2 pcs bootlid hinges (LH/RH)	@ S\$100.70	in 201.40	X
2 pcs bootlid hinges cover(LH/RH)		in 71.70	✓
1 pc bootlid logo		in 68.20	✓
1 pc bootlid "LEXUS" emblem		in 110.00	✓
1 pc bootlid "IS200T" emblem		in 237.90	508in
1 pc bootlid weatherstrip		in 499.00	✓
1 pc bootlid lock		in 45.00	X
1 pc bootlid lock catch	@ S\$ 15.00	in 60.00	X
4 pcs bootlid rubber stopper		in 454.80	X
1 pc bootlid inner trim	@ S\$ 5.50	in 55.00	✓
10 pcs bootlid inner trim clips	@ S\$560.50	in 1,121.00	?
2 pcs bootlid lamp (LH/RH)		in 149.70	X
1 pc bootlid outer garnish	@ S\$161.70	in 323.40	X
2 pcs bootlid outer garnish lamp cover (LH/RH)	@ S\$733.20	in 1,466.40	?
2 pcs taillamp assy (LH/RH)	@ S\$125.40	in 250.80	X
2 pcs taillamp retainer (LH/RH)		in 811.90	✓
1 pc rear end panel			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SFK 933 D
Our Ref : 020405

Page : 2
No. : 31391

- 1 pc rear end panel top garnish
- 1 pc spare tyre lock screw
- 1 pc spare tyre panel top board
- 2 pcs spare tyre panel top sponge compartment (LH/RH)
- 2 pcs spare tyre panel top side board
- 4 pcs spare tyre panel top side board rope hook
- 1 pc rear floor panel undercover

	Bu	349.70	✓
		85.90	7
	Ln	790.30	X
@ S\$258.00		516.00	7
@ S\$287.90		575.80	7
@ S\$ 74.00	Ln	296.00	X
		503.30	7
		16,354.20	
Less 10% :		-1,635.42	
		14,718.78	

Ln 40.00 sn X

- 1 pc rear number plate

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

800.00 600l

To focus taillamps. To check rear wiring and lighting operation.

50.00 20l

To remove and refit rear upholstery trimming, roof lining, seats, speaker board in order to facilitate repairing works

120.00 60l

120.00 60l

To apply undersealing

To remove and refit reverse sensor assy.

80.00 60l

To putty and respray on affected portions.

750l
1,200.00

Total : S\$17,128.78
=====

Singapore Dollars Seventeen Thousand One Hundred and Twenty Eight and Cents Seventy Eight Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.