

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 31391

Vehicle Insured : SFK 933 D
Accident Date : 30-Aug-2020

Date : 01-Sep-2020

Our Ref : 020405 (AIG ASIA) / QUEK

PAGE : 1

SHANEET NITYANAND RAI (MR)
Singapore

@ 10,129.13

Not Authorized

Repair After Paint

5 days

ESTIMATED COST OF REPAIR FOR LEXUS IS200T EXECUTIVE(1998cc)-2016 SLA2176R

2 pcs rear number plate lamp assy (LH/RH)	@ S\$161.70	323.40	X
1 pc rear bumper - top		1,061.80	✓
2 pcs rear bumper side retainer (LH/RH)	@ S\$145.00	290.00	✓
10 pcs rear bumper clips	@ S\$ 5.50	55.00	✓
1 pc rear bumper - bottom		503.30	✓
2 pcs rear bumper reflector(LH/RH)	@ S\$167.80	335.60	X
2 pcs rear bumper parking sensor	@ S\$490.80	1,963.20	24T 0475 X2 950.00
1 pc rear bumper sponge		112.40	✓
1 pc rear bumper reinforcement		485.00	✓
1 pc bootlid		1,733.90	✓
2 pcs bootlid hinges (LH/RH)	@ S\$223.70	447.40	X
2 pcs bootlid hinges cover(LH/RH)	@ S\$100.70	201.40	X
1 pc bootlid logo		71.70	✓
1 pc bootlid "LEXUS" emblem		68.20	✓
1 pc bootlid "IS200T" emblem		110.00	✓
1 pc bootlid weatherstrip		237.90	508.11 118.95.00
1 pc bootlid lock		499.00	✓
1 pc bootlid lock catch		45.00	X
4 pcs bootlid rubber stopper	@ S\$ 15.00	60.00	X
1 pc bootlid inner trim		454.80	X
10 pcs bootlid inner trim clips	@ S\$ 5.50	55.00	✓
2 pcs bootlid lamp (LH/RH)	@ S\$560.50	1,121.00	901.00
1 pc bootlid outer garnish		149.70	X
2 pcs bootlid outer garnish lamp cover (LH/RH)	@ S\$161.70	323.40	X
2 pcs taillamp assy (LH/RH)	@ S\$733.20	1,466.40	✓
2 pcs taillamp retainer (LH/RH)	@ S\$125.40	250.80	X
1 pc rear end panel		811.90	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : SFK 933 D
Our Ref : 020405

Page : 2
No. : 31391

- 1 pc rear end panel top garnish
- 1 pc spare tyre lock screw
- 1 pc spare tyre panel top board
- 2 pcs spare tyre panel top sponge compartment (LH/RH)
- 2 pcs spare tyre panel top side board
- 14 pcs spare tyre panel top side board rope hook
- 1 pc rear floor panel undercover

	Bu	349.70	✓
	CM	85.90	✓
	Sn	790.30	X
@ S\$258.00	Sn	516.00	X
@ S\$287.90	Sn	575.80	X
Del @ S\$ 74.00	Sn	296.00	X
	Sn	503.30	X
		16,354.20	
Less 10% :		-1,635.42	
		14,718.78	

- 1 pc rear number plate

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

800.00 600

To focus taillamps. To check rear
wiring and lighting operation.

50.00 200

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

120.00 600

120.00 600

To apply undersealing

To remove and refit reverse sensor
assy.

80.00 600

To putty and respray on affected
portions.

7500
1,200.00

Total : S\$17,128.78
=====

Singapore Dollars Seventeen Thousand One Hundred
and Twenty Eight and Cents Seventy Eight Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.