

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 07 Sep 2020

Preliminary Advice

Vehicle No	: SKV1663J	Accident Date	: 28/08/2020
Make	: AUDI A4	Policy No.	: 2100427526
Assignment Date	: 01/09/2020	Excess	: S\$800.00
Date of Inspection	: 01/09/2020	Est. Duration of Repair	: 9
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,038.00	(ESTIMATE \$43,036.00 + SUPPLEMENTARY \$1,002.00)
Revised Amount	:S\$	15,826.00	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	19,750.00	
Total	:S\$	35,576.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	48,391.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,609.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER ABLE TO UNDERTAKE AT REPAIR COST \$19,500.00.