

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 47197

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0612/2020/NS
Date : 29-Aug-20

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle n : SKV 1663 J

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

6 days - ok - Jy - 29 Jan 21

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Ong Tar Gin
Address : 66 Marine Parade Road
#16-13
Singapore 449300
Telephone : HP +65 90469511
Type of Claim : Own Damage Claim
Policy No. : 2100427526-04
Vehicle No : **SKV 1663 J**
Model Code : Audi A4 1.8T FSI MU 8K203
Model / Year : Aug-15
Engine No : CJE 108592
Chassis No : WAUZZZ8K8FA160411
Mileage : 60863KM
Date In : 28-Aug-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Aug-20
Place of Accident : Blk 28 Cassia Crescent

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKV 1663 J

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To tow vehicle from accident scene.	S/N \$	280.00	
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 280.00
3	To remove and transfer rhs headlight control unit and power module.	S/N \$	350.00	\$ 250.00
4	To remove and reinstall aircon condenser, charged air cooler and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00	
5	To dismantle and renew front bumper, rhs front fender, and rhs headlight. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$	4,200.00	\$ 1,000.00
6	To respray front bumper, bonnet and rhs front fender.	\$	3,000.00	\$ 1,650.00
7	To renew rhs front rim with tyre. To carry out wheel alignment.	S/N \$	280.00	\$ 280.00
8	To remove and renew rhs front wheel suspension assy.	S/N \$	1,800.00	
9	To carry out pre-wheel alignment.	S/N \$	240.00	\$ 240.00 X
10	To carry out pre and post diagnostic check.	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 12,094.00	\$ 4,084.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 1663 J

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,278.00	\$ 1,822.40
2	FRONT BUMPER FIXING PARTS	\$ 256.00	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 225.00	\$ 180.00
4	FRONT BUMPER GRILLE - LOWER CENTRE	\$ 136.00	\$ 106.80
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	\$ 192.00	
6	FRONT BUMPER SUPPORT ELEMENT - UPPER	\$ 59.00	
7	RADIATOR GRILLE	\$ 1,077.00	\$ 861.60
8	FRONT BUMPER VENT GRILLE - RH	\$ 134.00	
9	FRONT WHEEL SPOILER - RH	\$ 51.00	\$ 40.16
10	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 870.00	
11	FRONT BUMPER FOAM FILLER PIECE	\$ 123.00	
12	FOAM FILLER PIECE COVER	\$ 126.00	
13	FRONT BUMPER GUIDE SECTION - RH	\$ 36.00	\$ 28.48
14	CAUTION SIGN STICKER	NEC \$ 14.00	
15	AIRCON STICKER	NEC \$ 24.00	
16	FRONT BUMPER SUPPORT	2 \$ 25.00	\$ 19.84
17	SIGNAL HORN - LOW TONE RH	\$ 199.00	
18	SPRING SHACKLE - RH LOW TONE	\$ 24.00	
19	FRONT FENDER - RH	\$ 979.00	\$ 782.80
20	FRONT FENDER ATTACHMENT PARTS	\$ 57.00	
SUB TOTAL SPARE PARTS CHARGES		: \$ 6,885.00	\$ 3,842.08

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6386 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 1663 J

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/Nett	Remarks
	<i>c/f</i>		\$ 3,842.08
21	FRONT FENDER BRACKET - RH FRONT	\$ 52.00	\$ 41.36
22	DEFORMATION ELEMENT BRACKET - RH REAR	\$ 49.00	
23	FRONT FENDER BRACE - RH LOWER	\$ 117.00	\$ 93.60
24	FRONT FENDER CLOSING ELEMENT - RH	\$ 127.00	
25	WHEEL HOUSING LINER	\$ 237.00	\$ 189.20
26	WHEEL HOUSING GLINER ATTACHMENT PARTS	\$ 44.00	
27	STONE CHIP GUARD	\$ 72.00	\$ 57.36
28	ADHESIVE TAPE	\$ 54.00	\$ 43.04
29	HEADLIGHT MOUNTING - RH	\$ 117.00	\$ 93.60
30	HEADLIGHT - RH	\$ 2,316.00	\$ 1,852.80
31	HEADLAMP BRACKET - RH	\$ 105.00	\$ 83.60
32	HEADLIGHT RETAINING PLATE - RH	\$ 24.00	
33	DAY DRIVING LIGHTS POWER MODULE	\$ 538.00	
34	GAS DISCHARGE LAMP	\$ 408.00	
35	GAS DISCHARGE LAMP CONTROL UNIT	\$ 1,084.00	
36	HEADLIGHT HOSE - RH	\$ 36.00	
37	HALOGEN FOG LAMP - RH	\$ 259.00	
38	LIFT CYLINDER - RH	\$ 208.00	\$ 166.00
39	LIFT CYLINDER HOSE	\$ 175.00	
40	FRONT ALUMINIUM RIM - RH	\$ 715.00	\$ 572.00
SUB TOTAL SPARE PARTS CHARGES		: \$ 6,737.00	\$ 7,034.64

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 1663 J

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
		c/f		\$ 7,034.64
41	RADIAL TYRE		\$ 1,021.00	
42	LOCK CARRIER		\$ 1,004.00	
43	LOCK CARRIER BRACE - RH		\$ 45.00	
44	COOLANT REGULATOR SUPPORT		\$ 38.00	
45	READY MIX COOLANT		\$ 91.00	
46	RADIATOR AIR GUIDE - RH		\$ 26.00	
47	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
48	FRONT WISHBONE LINK - RH		\$ 533.00	
49	FRONT SUSPENSION GUIDE - RH		\$ 988.00	
50	FRONT SUSPENSION GUIDE - FRONT / REAR RH	2	\$ 1,066.00	
51	WHEEL BEARING HOUSING - RH		\$ 1,123.00	
52	SWIVEL JOINT		\$ 191.00	
53	WHEEL HUB		\$ 463.00	
54	WHEEL BEARING ASSEMBLY		\$ 570.00	
55	COUPLING ROD		\$ 127.00	
56	ANTI-ROLL BAR		\$ 419.00	
57	SUSPENSION FORKS - RH		\$ 235.00	
58	GAS SHOCK ABSORBER		\$ 301.00	
59	DRIVE SHAFT - RH		\$ 2,620.00	
60	STEERING GEAR		\$ 5,826.00	
SUB TOTAL SPARE PARTS CHARGES			\$ 16,747.00	\$ 7,094.64

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
		c/f		\$ 7,094.64
61	TRACK ROD		\$ 98.00	
62	TIE ROD END - RH		\$ 175.00	
63	SUPPLEMENTARY		\$ 1,002.00	\$ 800.40
64	SUNDRIES		\$ 300.00	\$ 23.20
	TOTAL SPARE PARTS CHARGES	:	\$ 31,944.00	\$ 7,918.24
	TOTAL LABOUR CHARGES	:	\$ 12,094.00	\$ 4,084.00
	GRAND TOTAL	:	\$ 44,038.00	\$ 12,002.24

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Netl



PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0612/2020/NS
Date 04-Sep-20
Service Advisor Glory Tan
Pages 1 of 1
Regn No SKV 1663 J
Model No Audi A4 1.8T FSI MU 8K203

Quantity	Description	Unit Price	Amount
Parts			
1	Headlight socket RHS	\$ 30.00	\$ 23.60
2	Air intake filter	\$ 344.00	\$ 274.80
3	Noise insulation	\$ 628.00	\$ 502.00

TOTAL

\$ 1,002.00 \$ 800.40

For Premium Automobiles Pte Ltd

Authorised Signature