

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 47197

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0612/2020/NS
Date	:	29-Aug-20

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle n : SKV 1663 J

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Ong Tar Gin
Address	:	66 Marine Parade Road #16-13 Singapore 449300
Telephone	:	HP +65 90469511
Type of Claim	:	Own Damage Claim
Policy No.	:	2100427526-04
Vehicle No	:	SKV 1663 J
Model Code	:	Audi A4 1.8T FSI MU 8K203
Model / Year	:	Aug-15
Engine No	:	CJE 108592
Chassis No	:	WAUZZZ8K8FA160411
Mileage	:	60863KM
Date In	:	28-Aug-20
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	28-Aug-20
Place of Accident	:	Blk 28 Cassia Crescent

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6356 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKV 1663]

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To tow vehicle from accident scene.	S/N S	280.00	X
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N S	360.00	280. ✓
3	To remove and transfer rhs headlight control unit and power module.	S/N S	350.00	250 ✓
4	To remove and reinstall aircon condenser, charged air cooler and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N S	1,200.00	? X
5	To dismantle and renew front bumper, rhs front fender, and rhs headlight. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	S	4,200.00	1000 (Without lock carrier) 2250 (with lock carrier)
6	To respray front bumper, bonnet and rhs front fender.	S	3,000.00	1650 ✓
7	To renew rhs front rim with tyre. To carry out wheel alignment.	S/N S	280.00	✓
8	To remove and renew rhs front wheel suspension assy.	S/N S	1,800.00	1800 ? X
9	To carry out ^{Post} pre wheel alignment.	S/N S	240.00	? X X
10	To carry out pre and post diagnostic check.	S/N S	384.00	✓
TOTAL LABOUR CHARGES		:	\$ 12,094.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 1663 J

S/N	Parts Description		Damage Parts & Prices		Remarks
			S/Nett		
1	FRONT BUMPER <i>Dislnd</i>	\$	2,278.00	✓	<i>1822.40</i>
2	FRONT BUMPER FIXING PARTS	\$	256.00	X	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Dislnd</i>	\$	225.00	✓	<i>180</i>
4	FRONT BUMPER GRILLE - LOWER CENTRE <i>Dislnd</i>	\$	136.00	✓	<i>106.40</i>
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>Not nec</i>	\$	192.00	X	
6	FRONT BUMPER SUPPORT ELEMENT - UPPER <i>Not nec</i>	\$	59.00	X	
7	RADIATOR GRILLE <i>Dislnd</i>	\$	1,077.00	✓	<i>861.60</i>
8	FRONT BUMPER VENT GRILLE - RH <i>Not nec</i>	\$	134.00	X	
9	FRONT WHEEL SPOILER - RH <i>Not nec</i>	\$	51.00	✓	<i>40.16</i>
10	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>Not nec</i>	\$	870.00	X	
11	FRONT BUMPER FOAM FILLER PIECE <i>Not nec</i>	\$	123.00	X	
12	<i>Front Bumper Top</i> FOAM FILLER PIECE COVER <i>Not nec</i>	\$	126.00	X	
13	FRONT BUMPER GUIDE SECTION - RH <i>Dislnd</i>	\$	36.00	✓	<i>28.48</i>
14	CAUTION SIGN STICKER <i>Not nec</i>	NEC \$	14.00	X	
15	AIRCON STICKER <i>Not nec</i>	NEC \$	24.00	X	
16	FRONT BUMPER SUPPORT <i>Dislnd</i>	2 \$	25.00	✓	<i>19.44</i>
17	SIGNAL HORN - LOW TONE RH <i>Not nec</i>	\$	199.00	X	
18	SPRING SHACKLE - RH LOW TONE <i>Not nec</i>	\$	24.00	X	
19	FRONT FENDER - RH <i>Dislnd</i>	\$	979.00	✓	<i>782.80</i>
20	FRONT FENDER ATTACHMENT PARTS <i>Not nec</i>	\$	57.00	X	
SUB TOTAL SPARE PARTS CHARGES			:	\$	<u>6,885.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 1663]

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	FRONT FENDER BRACKET - RH FRONT <i>Best</i>	\$ 52.00	✓ <i>41.36</i>
22	DEFORMATION ELEMENT BRACKET - RH REAR <i>new</i>	\$ 49.00	✗
23	FRONT FENDER BRACE - RH LOWER <i>Best</i>	\$ 117.00	✓ <i>93.60</i>
24	FRONT FENDER CLOSING ELEMENT - RH <i>Not nec</i>	\$ 127.00	? ✗
25	WHEEL HOUSING LINER <i>Torn</i>	\$ 237.00	✓ <i>189.20</i>
26	WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not nec</i>	\$ 44.00	? ✗
27	STONE CHIP GUARD <i>new</i>	\$ 72.00	✓ <i>57.36</i>
28	ADHESIVE TAPE <i>new</i>	\$ 54.00	✓ <i>43.04</i>
29	HEADLIGHT MOUNTING - RH <i>incl</i>	\$ 117.00	✓ <i>93.60</i>
30	HEADLIGHT - RH <i>incl</i>	\$ 2,316.00	✓ <i>1852.80</i>
31	HEADLAMP BRACKET - RH <i>incl</i>	\$ 105.00	✓ <i>83.60</i>
32	HEADLIGHT RETAINING PLATE - RH <i>Not nec</i>	\$ 24.00	? ✗
33	DAY DRIVING LIGHTS POWER MODULE <i>Not nec</i>	\$ 538.00	? ✗
34	GAS DISCHARGE LAMP <i>new</i>	\$ 408.00	✗
35	GAS DISCHARGE LAMP CONTROL UNIT <i>Not nec</i>	\$ 1,084.00	? ✗
36	HEADLIGHT HOSE - RH <i>Not nec</i>	\$ 36.00	✗
37	HALOGEN FOG LAMP - RH <i>new</i>	\$ 259.00	✗
38	LIFT CYLINDER - RH <i>Damaged</i>	\$ 208.00	✓ <i>166</i>
39	LIFT CYLINDER HOSE <i>new</i>	\$ 175.00	✗
40	FRONT ALUMINIUM RIM - RH <i>cut</i>	\$ 715.00	✓ <i>572</i>
SUB TOTAL SPARE PARTS CHARGES		: \$ 6,737.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 1663 J

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
		\$	1,021.00 X.
41	RADIAL TYRE <i>Not m</i>	\$	1,004.00 ? X
42	LOCK CARRIER <i>Not m</i>	\$	45.00 ? X
43	LOCK CARRIER BRACE - RH <i>Not m</i>	\$	38.00 ? X
44	COOLANT REGULATOR SUPPORT <i>Not m</i>	\$	91.00 ? X
45	READY MIX COOLANT <i>Not m</i>	\$	26.00 ? X
46	RADIATOR AIR GUIDE - RH <i>Not m</i>	\$	60.00 ✓
47	FRONT NO PLATE <i>Not m</i>	S/N \$	533.00 ? X
48	FRONT WISHBONE LINK - RH <i>Not m</i>	\$	988.00 ? X
49	FRONT SUSPENSION GUIDE - RH <i>Not m</i>	\$	1,066.00 ? X
50	FRONT SUSPENSION GUIDE - FRONT / REAR RH <i>Not m</i>	2 \$	1,123.00 ? X
51	WHEEL BEARING HOUSING - RH <i>Not m</i>	\$	191.00 ? X
52	SWIVEL JOINT <i>Not m</i>	\$	463.00 ? X
53	WHEEL HUB <i>Not m</i>	\$	570.00 ? X
54	WHEEL BEARING ASSEMBLY <i>Not m</i>	\$	127.00 ? X
55	COUPLING ROD <i>Not m</i>	\$	419.00 ? X
56	ANTI-ROLL BAR <i>Not m</i>	\$	235.00 ? X
57	SUSPENSION FORKS - RH <i>Not m</i>	\$	301.00 ? X
58	GAS SHOCK ABSORBER <i>Not m</i>	\$	2,620.00 X
59	DRIVE SHAFT - RH <i>Not m</i>	\$	5,826.00 ? X
60	STEERING GEAR <i>Not m</i>	\$	
SUB TOTAL SPARE PARTS CHARGES		:	\$ 16,747.00

Diagnostic Report,
photos -

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 16631

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
61	TRACK ROD <i>He Ne</i>	\$ 98.00	? X
62	TIE ROD END - RH <i>He Ne</i>	\$ 175.00	? X
63	SUNDRIES <i>Ne</i>	\$ 300.00	? <i>23.20</i> ✓
TOTAL SPARE PARTS CHARGES		:	\$ 30,942.00
TOTAL LABOUR CHARGES		:	\$ 12,094.00
GRAND TOTAL		:	\$ 43,036.00

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

06 Days -
R.S.



PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0612/2020/NS 4-Sep-20 Glory Tan 1 of 1 SKV 1663 J Audi A4 1.8T FSI MU 8K203
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Headlight socket RHS <i>Damage</i>	\$ 30.00	✓ 23.60
2	Air intake filter <i>cracked</i>	\$ 344.00	✓ 274.80
3	Noise insulation <i>torn</i>	\$ 628.00	✓ 502
TOTAL		\$ 1,002.00	

For Premium Automobiles Pte Ltd

Adrian Ling
07/09/20
[Signature]

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian

Surveyed Date

: 01/09/20

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorized / 06 Days (Without lock carrier)
09 Days (With lock carrier)

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant