

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	28 Aug 2020 17:07	Clm Veh Model Changed		[] Merimen Administrator
2	28 Aug 2020 17:07	Clm Created	Reg No: SKV1663J. Policy No: 2100427526-04. Acct Date: 2020/08/28. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA120074020	[I] Merimen Administrator
3	01 Sep 2020 17:20	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
4	01 Sep 2020 17:20	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
5	01 Sep 2020 17:20	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
6	01 Sep 2020 17:20	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/09/10	[A] LEE SU THING
7	01 Sep 2020 17:20	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] LEE SU THING
8	01 Sep 2020 17:20	Clm Registration Modified	Rep:1137->200611.	[A] LEE SU THING
9	01 Sep 2020 17:20	Clm Veh Model Changed	(202996) AUDI A4 1.8 TFSI MU (B8) (A).	[A] LEE SU THING
10	01 Sep 2020 17:20	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] LEE SU THING
11	02 Sep 2020 09:07	Clm Registration Modified	Acct Time:10:50:00->10:00:00. Pol No:2100427526-04->2100427526. Init.Est.->5,000 - 6,000.	[I] Subramaniam, Divyashni
12	02 Sep 2020 10:23	Adj Rpt Initiated		[A] SHIAU CHAN
13	02 Sep 2020 10:23	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] SHIAU CHAN
14	02 Sep 2020 10:23	Clm Dtl Modified	JPJ Reg. Date: -> 2015/08/31.	[A] SHIAU CHAN
15	02 Sep 2020 10:23	Clm Details Notified		[A] SHIAU CHAN
16	02 Sep 2020 10:57	Clm Registration Modified	2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Mithoo Singh, Aashweenjeet Kaur
17	02 Sep 2020 11:20	Clm Dtl Modified	Insured ID: 1311796I -> S1331796I.	[A] SHIAU CHAN
18	02 Sep 2020 11:44	Clm Registration Modified	Excess: -> 800.00.	[I] Mithoo Singh, Aashweenjeet Kaur
19	02 Sep 2020 11:44	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
20	02 Sep 2020 15:42	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2020/09/10	[A] SHIAU CHAN
21	02 Sep 2020 15:43	Adj Mandate Request	Cur.Req:34574.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. REPAIRER ABLE TO UNDERTAKE AT REPAIR COST \$19,500.00. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
22	03 Sep 2020 08:50	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/09/10. Mandate Remarks: Authorise repair. Repair limit at \$19,500.00. Number plate not damage to take out. LIFT CYLINDER - RH - resurvey damage photos. Re-inspection to be done for damage check and supplementary items /	[I] Koh, Victor-CK
23	03 Sep 2020 08:50	Adj Mandate Set	Approved:14824.00:Authorise repair. Repair limit at \$19,500.00. Number plate not damage to take out. LIFT CYLINDER - RH - resurvey damage photos. Re-inspection to be done for damage check and supplementary items / labour with clear photos. Reinsp:	[I] Koh, Victor-CK

Date From  Date To  Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2575800	02 Sep 2020 10:23:40	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKV1663J		11.00