



BAN HOCK HIN
Co., Pte Ltd

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 36630

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN: MS FIRST CAPITAL INSURANCE LTD

DATE : 12/08/2020
CLAIM NO. : 11598
POLICY NO. : MC/00793194

FROM : HASRIANAH

VEHICLE NO. : FBP9607H
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 5)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	Repair	1.00	\$700.00	700.00
2	AXLE FRONT WHEEL P/N: 59126	REPLACE	1.00	\$14.00	14.00
3	BALANCER P/N: 55166	REPLACE	2.00	\$10.00	20.00
4	BAR HANDLE P/N: 58072	REPLACE	1.00	\$31.00	31.00
5	BEARING 6300-2NS (NACHI) P/N: 38347	REPLACE	2.00	\$14.00	28.00
6	BEARING STEERING CONE LOWER P/N: 58120	REPLACE	1.00	\$12.00	12.00
7	BEARING STEERING CONE UPPER P/N: 36392	REPLACE	1.00	\$41.00	41.00
8	BELLY PAN P/N: 58094	REPLACE	1.00	\$33.00	33.00
9	BOARD FOOTREST LH P/N: 59588	REPLACE	1.00	\$50.00	50.00
10	BOARD FOOTREST RH P/N: 59589	REPLACE	1.00	\$50.00	50.00
11	BOX FILTER AIR OUTER P/N: 58141	REPLACE	1.00	\$17.00	17.00
12	BOX FILTER AIR OUTER FRONT P/N: 58164	REPLACE	1.00	\$10.00	10.00
13	BRACKET BAR HANDLE P/N: 58191	REPLACE	1.00	\$38.00	38.00
14	COVER BAR HANDLE LOWER P/N: 64731	REPLACE	1.00	\$16.00	16.00

*36630

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
15	COVER CLUTCH OUTER P/N: 58147	REPLACE	1.00	\$27.00	CN7 27.00
16	COVER CLUTCH OUTER DAMPER 1 P/N: 58111	REPLACE	1.00	\$12.00	NR 12.00
17	COVER CLUTCH OUTER DAMPER 2 P/N: 58172	REPLACE	1.00	\$7.00	NR 7.00
18	COVER CLUTCH OUTER DAMPER 3 P/N: 58107	REPLACE	1.00	\$7.00	NR 7.00
19	COVER CLUTCH OUTER DAMPER 4 P/N: 58140	REPLACE	1.00	\$12.00	NR 12.00
20	COVER FRONT LOWER(GREY) P/N: 63494	REPLACE	1.00	\$11.00	CN9 11.00
21	COVER FRONT UPPER P/N: 63498	REPLACE	1.00	\$38.00	CN9 38.00
22	COVER LEG SHIELD P/N: 60933	REPLACE	1.00	\$16.00	CN 16.00
23	COVER RADIATOR P/N: 63127	REPLACE	1.00	\$21.00	CN7 21.00
24	COVER SIDE CENTRE LH (GREY) P/N: 63488	REPLACE	1.00	\$28.00	CN7 28.00
25	COVER SIDE LH (MATTE BLACK) P/N: 66090	REPLACE	1.00	\$70.00	CN7 70.00
26	DAMPER COMPARTMENT SEAT RH P/N: 60914	REPLACE	1.00	\$9.00	NR 9.00 X
27	EMBLEM (YAMAHA) LOGO P/N: 57069	REPLACE	2.00	\$10.00	NR 20.00
28	FENDER INNER P/N: 59583	REPLACE	1.00	\$28.00	CN9 28.00
29	FOOTREST REAR ASSY 1 LH P/N: 58212	REPLACE	1.00	\$31.00	NR 31.00
30	FORK FRONT ASSY P/N: 59590	REPLACE	1.00	\$741.00	3A/1/1 741.00
31	FRONT COWLING LH (GREY) P/N: 63489	REPLACE	1.00	\$20.00	CN 20.00
32	FRONT COWLING RH (GREY) P/N: 63499	REPLACE	1.00	\$20.00	CN9 20.00
33	HEADLAMP ASSY P/N: 58174	REPLACE	1.00	\$299.00	CN9/SCR 299.00
34	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	20.00	\$63.00	400 1,260.00
35	LAMP SIGNAL FRONT LH P/N: 59587	REPLACE	1.00	\$34.00	CN9 34.00
36	LAMP SIGNAL FRONT RH P/N: 59592	REPLACE	1.00	\$34.00	SCR 34.00

*36630 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
37	LEG SHIELD ASSY P/N: 60917	REPLACE	1.00	\$33.00	33.00 ✓
38	LEVER BRAKE LH P/N: 58145	REPLACE	1.00	\$17.00	17.00 ✓
39	LEVER BRAKE RH P/N: 58185	REPLACE	1.00	\$17.00	17.00 ✓
40	MAT FLOOR BOARD LH P/N: 60922	REPLACE	1.00	\$17.00	17.00 ✓
41	METER IU (12V) NEW MODEL P/N: 34351	REPLACE	1.00	\$280.00	280.00 175 ✓
42	MID SEAL DUST P/N: 41201	REPLACE	1.00	\$9.00	9.00 ✓
43	MIRROR LH P/N: 58099	REPLACE	1.00	\$35.00	35.00 ✓
44	MIRROR RH P/N: 58187	REPLACE	1.00	\$35.00	35.00 ✓
45	MUDGUARD FRONT (GREY) P/N: 63496	REPLACE	1.00	\$28.00	28.00 ✓
46	NUT SPRING P/N: 53709	REPLACE	6.00	\$3.00	18.00 ✓
47	NUT SPRING P/N: 59586	REPLACE	8.00	\$2.00	16.00 ✓
48	PANEL 1 (MATTE BLACK) LH P/N: 63491	REPLACE	1.00	\$21.00	21.00 ✓
49	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	REPLACE	1.00	\$27.00	27.00 105.0 ✓
50	PROTECTOR EXHAUST P/N: 58086	REPLACE	1.00	\$37.00	37.00 ✓
51	RACE BALL 1 P/N: 55220	REPLACE	1.00	\$12.00	12.00 ✓
52	RACE BALL 2 P/N: 55216	REPLACE	1.00	\$12.00	12.00 ✓
53	RETAINER BALL BEARING P/N: 55215	REPLACE	1.00	\$12.00	12.00 ✓
54	RIM SPORT FRONT (BLACK) P/N: 66875	REPLACE	1.00	\$238.00	238.00 ✓
55	RIVET P/N: 56583	REPLACE	10.00	\$2.00	20.00 ✓
56	SEAL OIL P/N: 61482	REPLACE	2.00	\$2.00	4.00 ✓
57	SIDE STAND P/N: 58211	REPLACE	1.00	\$23.00	23.00 X
58	SPRAY PAINT ON CENTER COVER RH	Spray	1.00	\$91.00	91.00

*36630 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
59	SPRAY PAINT ON FRONT LOWER COVER RH <i>scr</i>	Spray <i>1</i>	1.00	\$91.00 <i>Local respray</i>	60 91.00
60	SPRAY PAINT ON FRONT PROTECTOR RH <i>scr</i>	Spray <i>1</i>	1.00	\$63.00 <i>Local respray</i>	35 63.00
61	SPRAY PAINT ON HANDLE SEAT REAR <i>scr</i>	Spray <i>1</i>	1.00	\$42.00 <i>Local respray</i>	42.00 ✓
62	SPRAY PAINT ON TAIL COVER LH <i>scr</i>	Spray <i>1</i>	1.00	\$63.00 <i>Local respray</i>	45 63.00
63	SPRAY PAINT ON TAIL COVER RH <i>scr</i>	Spray <i>1</i>	1.00	\$63.00 <i>Local respray</i>	45 63.00
64	STAND MAIN P/N: 58138	REPLACE	1.00	\$63.00	2 63.00 X
65	STAY FRONT HEADLAMP P/N: 60938	REPLACE	1.00	\$90.00	1 90.00 ✓
66	STICKER (MCDONALD)COVER SIDE P/N: 60256	REPLACE <i>1</i>	2.00	\$17.00	ner 34.00 <i>scr</i>
67	STICKER (MCDONALDS) SIDECOVER/WINDSHIELD P/N: 56222	REPLACE <i>1</i>	1.00	\$16.00	ner 16.00 <i>scr</i>
68	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE <i>1</i>	1.00	\$19.00	ner 19.00 <i>scr</i>
69	STOPPER P/N: 51526	REPLACE	2.00	\$5.00	ner 10.00
70	STOPPER MAINSTAND P/N: 54930	REPLACE	1.00	\$16.00	ner 16.00 X
71	TRANSPORT CHARGES P/N: 07169	<i>1</i>	1.00	\$56.00	35 56.00
72	VALVE RIM P/N: 27762	REPLACE	1.00	\$13.00	ner 13.00 ✓
73	WINDSHIELD P/N: 58073	REPLACE	1.00	\$56.00	one 56.00

SUB TOTAL

\$5,502.00

GST @ 7 %

\$385.14

GRAND TOTAL (SGD)

\$5,887.14

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



HASRIANAH

*36630 *

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

P. 2586
102
2327.40
976
3303.40

bizSAFE₃CERT NO.: 2002-14783
ISO 9001: 2015



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 19700288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 36630

- Rev. 2

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN: MOTOR CLAIMS DEPT

DATE : 12/08/2020
CLAIM NO. : 11598
POLICY NO. : MC/00793194
FROM : HASRIANAH

VEHICLE NO. : FBP9607H
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE FRONT WHEEL P/N: 59126	REPLACE	1.00	\$14.00 Disc %: 10.00	12.60 18.00
2	BALANCER P/N: 55166	REPLACE	2.00	\$10.00 Disc %: 10.00	27.90
3	BAR HANDLE P/N: 58072	REPLACE	1.00	\$31.00 Disc %: 10.00	25.20
4	BEARING 6300-2NS (NACHI) P/N: 38347	REPLACE	2.00	\$14.00 Disc %: 10.00	10.80
5	BEARING STEERING CONE LOWER P/N: 58120	REPLACE	1.00	\$12.00 Disc %: 10.00	36.90
6	BEARING STEERING CONE UPPER P/N: 36392	REPLACE	1.00	\$41.00 Disc %: 10.00	29.70
7	BELLY PAN P/N: 58094	REPLACE	1.00	\$33.00 Disc %: 10.00	45.00
8	BOARD FOOTREST LH P/N: 59588	REPLACE	1.00	\$50.00 Disc %: 10.00	45.00
9	BOARD FOOTREST RH P/N: 59589	REPLACE	1.00	\$50.00 Disc %: 10.00	15.30
10	BOX FILTER AIR OUTER P/N: 58141	REPLACE	1.00	\$17.00 Disc %: 10.00	9.00
11	BOX FILTER AIR OUTER FRONT P/N: 58164	REPLACE	1.00	\$10.00 Disc %: 10.00	34.20
12	BRACKET BAR HANDLE P/N: 58191	REPLACE	1.00	\$38.00 Disc %: 10.00	14.40
13	COVER BAR HANDLE LOWER P/N: 64731	REPLACE	1.00	\$16.00 Disc %: 10.00	24.30
14	COVER CLUTCH OUTER P/N: 58147	REPLACE	1.00	\$27.00 Disc %: 10.00	

*36630 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-14383
ISO 18001:2015

S/N	Description	Action	Qty	Unit Price	Amount
15	COVER CLUTCH OUTER DAMPER 1 P/N: 58111	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
16	COVER CLUTCH OUTER DAMPER 2 P/N: 58172	REPLACE	1.00	\$7.00 Disc %: 10.00	6.30
17	COVER CLUTCH OUTER DAMPER 3 P/N: 58107	REPLACE	1.00	\$7.00 Disc %: 10.00	6.30
18	COVER CLUTCH OUTER DAMPER 4 P/N: 58140	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
19	COVER FRONT LOWER(GREY) P/N: 63494	REPLACE	1.00	\$11.00 Disc %: 10.00	9.90
20	COVER FRONT UPPER P/N: 63498	REPLACE	1.00	\$38.00 Disc %: 10.00	34.20
21	COVER LEG SHIELD P/N: 60933	REPLACE	1.00	\$16.00 Disc %: 10.00	14.40
22	COVER RADIATOR P/N: 63127	REPLACE	1.00	\$21.00 Disc %: 10.00	18.90
23	COVER SIDE CENTRE LH (GREY) P/N: 63488	REPLACE	1.00	\$28.00 Disc %: 10.00	25.20
24	COVER SIDE LH (MATTE BLACK) P/N: 66090	REPLACE	1.00	\$70.00 Disc %: 10.00	63.00
25	EMBLEM (YAMAHA) LOGO P/N: 57069	REPLACE	2.00	\$10.00 Disc %: 10.00	18.00
26	FENDER INNER P/N: 59583	REPLACE	1.00	\$28.00 Disc %: 10.00	25.20
27	FOOTREST REAR ASSY 1 LH P/N: 58212	REPLACE	1.00	\$31.00 Disc %: 10.00	27.90
28	FORK FRONT ASSY P/N: 59590	REPLACE	1.00	\$741.00 Disc %: 10.00	666.90
29	FRONT COWLING LH (GREY) P/N: 63489	REPLACE	1.00	\$20.00 Disc %: 10.00	18.00
30	FRONT COWLING RH (GREY) P/N: 63499	REPLACE	1.00	\$20.00 Disc %: 10.00	18.00
31	HEADLAMP ASSY P/N: 58174	REPLACE	1.00	\$299.00 Disc %: 10.00	269.10
32	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1.00	\$400.00	400.00
33	LAMP SIGNAL FRONT LH P/N: 59587	REPLACE	1.00	\$34.00 Disc %: 10.00	30.60
34	LAMP SIGNAL FRONT RH P/N: 59592	REPLACE	1.00	\$34.00 Disc %: 10.00	30.60
35	LEG SHIELD ASSY P/N: 60917	REPLACE	1.00	\$33.00 Disc %: 10.00	29.70
36	LEVER BRAKE LH P/N: 58145	REPLACE	1.00	\$17.00 Disc %: 10.00	15.30

*36630 *

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
37	LEVER BRAKE RH P/N: 58185	REPLACE	1.00	\$17.00 Disc %: 10.00	15.30
38	MAT FLOOR BOARD LH P/N: 60922	REPLACE	1.00	\$17.00 Disc %: 10.00	15.30
39	METER IU (12V) NEW MODEL P/N: 34351	REPLACE	1.00	\$175.00	175.00
40	MID SEAL DUST P/N: 41201	REPLACE	1.00	\$9.00 Disc %: 10.00	8.10
41	MIRROR LH P/N: 58099	REPLACE	1.00	\$35.00 Disc %: 10.00	31.50
42	MIRROR RH P/N: 58187	REPLACE	1.00	\$35.00 Disc %: 10.00	31.50
43	MUDGUARD FRONT (GREY) P/N: 63496	REPLACE	1.00	\$28.00 Disc %: 10.00	25.20
44	NUT SPRING P/N: 53709	REPLACE	6.00	\$3.00 Disc %: 10.00	16.20
45	NUT SPRING P/N: 59586	REPLACE	8.00	\$2.00 Disc %: 10.00	14.40
46	PANEL 1 (MATTE BLACK) LH P/N: 63491	REPLACE	1.00	\$21.00 Disc %: 10.00	18.90
47	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	REPLACE	1.00	\$10.00	10.00
48	PROTECTOR EXHAUST P/N: 58086	REPLACE	1.00	\$37.00 Disc %: 10.00	33.30
49	RACE BALL 1 P/N: 55220	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
50	RACE BALL 2 P/N: 55216	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
51	RETAINER BALL BEARING P/N: 55215	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
52	RIM SPORT FRONT(BLACK) P/N: 66875	REPLACE	1.00	\$238.00 Disc %: 10.00	214.20
53	RIVET P/N: 56583	REPLACE	10.00	\$2.00 Disc %: 10.00	18.00
54	SEAL OIL P/N: 61482	REPLACE	2.00	\$2.00 Disc %: 10.00	3.60
55	SPRAY PAINT ON CENTER COVER RH	Spray	1.00	\$60.00	60.00
56	SPRAY PAINT ON FRONT LOWER COVER RH	Spray	1.00	\$60.00	60.00
57	SPRAY PAINT ON FRONT PROTECTOR RH	Spray	1.00	\$35.00	35.00
58	SPRAY PAINT ON HANDLE SEAT REAR	Spray	1.00	\$42.00	42.00

*36630 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
59	SPRAY PAINT ON TAIL COVER LH	Spray	1.00	\$45.00	45.00
60	SPRAY PAINT ON TAIL COVER RH	Spray	1.00	\$45.00	45.00
61	STAY FRONT HEADLAMP P/N: 60938	REPLACE	1.00	\$90.00 Disc %: 10.00	81.00
62	STICKER (MCDONALD)COVER SIDE P/N: 60256	REPLACE	2.00	\$17.00	34.00
63	STICKER (MCDONALDS) SIDECOVER/WINDSHEILD P/N: 56222	REPLACE	1.00	\$16.00	16.00
64	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$19.00	19.00
65	STOPPER P/N: 51526	REPLACE	2.00	\$5.00 Disc %: 10.00	9.00
66	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00
67	VALVE RIM P/N: 27762	REPLACE	1.00	\$13.00 Disc %: 10.00	11.70
68	WINDSHIELD P/N: 58073	REPLACE	1.00	\$56.00 Disc %: 10.00	50.40
SUB TOTAL					\$3,303.40
GST @ 7 %					\$231.24
GRAND TOTAL (SGD)					\$3,534.64

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*36630 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
 Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-1-0383
 ISO 9001 2015