

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

1-Sep-20

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6178 X

1 pc	Boot lid	\$	1,119.00 <i>Ry</i>
1 pc	Boot lid lock	\$	99.00 x
1 pc	Bootlid striker	\$	21.00 x
1 pc	Bootlid emblem	\$	27.00 <i>re</i>
1 pc	Bootlid CRDi	\$	29.00 <i>re</i>
1 pc	Boot lid rubber weatherstrip	\$	96.00 x
1 pc	Boot lid lower garnish	\$	290.00 x
2 pcs	Bootlid hinges @ \$66.00	\$	132.00 x
1 pc	End panel	\$	250.00 x
1 pc	End panel inner garnish	\$	74.00 x
1 pc	Rear bumper	\$	696.00 <i>de</i>
1 pc	Rear bumper lower cover	\$	206.00 <i>de</i>
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00 x
1 pc	Rear bumper inner sponge	\$	114.00 ?
1 pc	Rear bumper reinforcement	\$	607.00 ?
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	106.00 x
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00 x
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00 x
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00 x
		\$	4,088.00
		Less 10%	\$ 408.80
			\$ 3,679.20

### S/NETT

1 set	Rear bumper clips	\$	48.00 <i>30na</i>
1 set	End panel inner garnish clips	\$	30.00 x
1 set	Bootlid inner trim clips	\$	52.00 x
1 set	Bootlid lower garnish clips	\$	60.00 x
1 set	Bootlid stickers	\$	100.00 <i>re</i>
1 set	Reverse sensor	\$	280.00 <i>200na</i>
1 set	Floorboard compartment insulating paddings	\$	120.00 x
1 pc	Rear bumper top protector	\$	80.00 <i>re</i>

# ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6178 X

Towing Fee	\$ 50.00 ?
Sundry	\$ 50.00 <i>2000</i>
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 30.
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 X
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the floorboard etc	\$ 1,000.00 <i>200</i>
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel,	\$ 1,000.00 <i>400</i>
To apply rustproofing on the repaired and replaced panels.	\$ 200.00 X
	<hr/>
	\$ 7,049.20

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tanphk 97495449  
 WP' 1/9/2002 440  
 02 days  
 Resurvey. after repair  
 finish @ 11/11/2002

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: