

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 31369

Date : 27-Aug-2020

PAGE : 1

Vehicle Insured : SHB 3255 G
Accident Date : 26-Aug-2020

Our Ref : 020389 (FIRST) / QUEK


GENE CHOW SOON HEE (MR)
Singapore

Not Authorized
Return B4 paint 4 days

ESTIMATED COST OF REPAIR FOR KIA CERATO K3 1.6A SUNROOF (2018) SLW9608A
=====

		<i>Bu</i>	668.20	✓
1 pc rear bumper			66.00	✓
2 pcs rear bumper side retainer (LH/RH)	<i>M/S</i> @ S\$ 33.00		32.00	✓
2 pcs rear bumper side bracket (LH/RH)	@ S\$ 16.00			
1 pc rear bumper - lower		<i>Bu</i>	347.00	✓
2 pcs rear bumper reflector (LH/RH)	<i>M/S</i> @ S\$ 99.00		198.00	✓
1 pc rear bumper under cover			40.00	✓
4 pcs rear bumper under cover clips	@ S\$ 4.00		16.00	✓
1 pc rear bumper reinforcement			313.00	✓
2 pcs rear bumper reinforcement bracket (LH/RH)	@ S\$140.00		280.00	✓
2 pcs rear bumper lower bracket (LH/RH)	@ S\$ 8.00	<i>Bu</i>	16.00	X
2 pcs rear bumper upper bracket (LH/RH)	@ S\$ 4.00		8.00	✓
4 pcs rear bumper parking sensor	@ S\$177.00		708.00	✓
1 pc rear bumper parking sensor wireharness		<i>Bu</i>	216.00	X
1 pc bootlid		<i>Bu</i>	1,297.00	✓
1 pc bootlid logo		<i>M</i>	24.00	✓
1 pc bootlid "CERATO" emblem		<i>M</i>	29.00	✓
1 pc bootlid "K3" emblem		<i>M</i>	60.00	✓
1 pc bootlid lock		<i>R</i>	109.00	X
1 pc rear end panel			315.00	✓
1 pc rear end panel top garnish		<i>Bu</i>	58.00	X
			4,800.20	
	Less 10% :		-480.02	
			4,320.18	

Con't Page 2 ...



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : SHB 3255 G
Our Ref : 020389

Page : 2
No. : 31369

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

800.00 50d

To apply undersealing

80.00 3d

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

120.00 7

To putty and respray on affected
portions.

900.00 60d

Total : S\$ 6,220.18
=====

Singapore Dollars Six Thousand Two Hundred and
Twenty and Cents Eighteen Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: