



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20009310/EUyf3e2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 18-09-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBM 1467M	Veh. Inspected	SJU 3797K	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2002569/LOR	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	02/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SUNNY	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JN1CFAN16Z0132369	Colour	SILVER	
Odometer	280554	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/50 R15	MICHELIN	5 mm	
L/H Front Tyre	185/50 R15	MICHELIN	5 mm	
R/H Rear Tyre	185/50 R15	MICHELIN	5 mm	
L/H Rear Tyre	185/50 R15	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/09/2020	Inspection Date	02/09/2020	
Survey held at	RYDER AUTO WORKSHOP LLP 2 Kaki Bukit Ave 2# 02-19 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		