

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SJU3797K

Accident Date : 1/9/20

Location : BKE TOWARDS SLE

Model: NISSAN SUNNY 1.6EXM
(2/3/2009)

3P: FBM1467M (SOMPO)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper / DEF	-	-	619.10
2	10 pcs	Rear bumper clips / MC	-	20.00	-
3	2 pcs	Rear bumper o/s & n/s retainer / BR	-	-	76.60
4	1 pc	Rear end panel X R	-	-	427.40
5	1 pc	Rear end panel inner trim X NM	-	-	78.20
6	8 pcs	Rear end panel inner trim clips X NM	-	24.00	-
7	1 pc	Rear reverse sensor / Shaded	-	200.00	-
Sub-Total:			0.00	244.00	1,201.30
			30%	0%	10%
After Less %:			961.04	244.00	1081.17

	Labour		
1	To dismantle, straighten and welding rear damage parts	800.00	300
2	To spray painting.	600.00	400
3	To check wiring.	80.00	30
4	To remove and replace rear reverse sensor.	80.00	30
5	To re-seal anti-rust.	80.00	30
Sub-Total:		1,640.00	
Total:		3,926.21	
After Less 20%:		3,140.97	

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

biSAFE 8778 1999
24 hr accident call

Mobil 1



PAYNOW