

SUPER-ZEE MOTOR SERVICE

BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195 TEL: 6383 1913 FAX: 6383 9565
EMAIL: superzeemotor@gmail.com

31 Aug 2020

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

THIRD PARTY CLAIM

OWNER NAME : ANG POH LAE
VEHICLE REG NO : SLN 7480 K
DATE OF ACCIDENT : 28 AUG 2018
PLACE OF ACCIDENT : SERANGOON GARDEN WAY/BRIGHTON CRES
INVOLVING VEH NO : SJP2819P

We append herewith our estimate for the repair of Vehicle No SLN7480K as follows:

Materials Required

1 pc	Rear Bumper		S\$ 840.80	X
2 pcs	Rear Bumper Retainers	11	S\$ 82.60	X
1 pc	Rear RH Trim <i>Trim</i>	11	S\$ 289.60	X
1 pc	Rear Axle	11	S\$1,845.30	X
1 pc	Rear RH Wheel Bearing	11	S\$ 361.50	X
1 pc	Rear RH Shock Absorber	11	S\$ 273.20	X
1 pc	Rear RH Absorber Mounting	11	S\$ 71.30	X
1 pc	Rear RH Absorber Dust Cover	11	S\$ 39.50	X
1 pc	Rear RH Coil Spring	11	S\$ 184.80	X
1 pc	Rear RH Tyre Rim	(u)	S\$ 450.00	SN ✓
1 pc	Rear RH Tyre	SN	S\$ 250.00	SN X
1 pc	RH Sideskirt <i>Side skirt</i>	<i>Side skirt protectors</i> (u)	S\$ 471.30	✓
			S\$5,159.90	

Labour Charges

To dismantle & replace damaged parts, panelbeat where necessary	S\$ 550.00	250
To putty, apply primer & spraypaint affected portion	S\$ 650.00	400
To apply rustproofing on repaired, replaced panel	11 S\$ 150.00	X
Computerised wheel alignment	S\$ 120.00	60

SUPER-ZEE MOTOR SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Business Registration No. 47959700J