

FBC 7212 Y (Yamaha XZ)

Estimate Repair For Vehicle FBC 7212 Y (Suzuki XZ)

QTY	DESCRIPTION OF PARTS	PRICE
1 pc	Handle bar / BT	\$120.00
1 set	Handle bar balancer L/R < CH X NN	\$40.00
1 set	Hand guard L/R X NN PH - cut	\$80.00
1 pc	Brake lever / BR	\$45.00
1 pc	Clutch lever X NN	\$45.00
1 pc	Meter assy - cut	\$320.00
1 pc	Front windshield - CRA	\$120.00
1 pc	Headlamp cowling - CRA	\$140.00
1 pc	Front shield X NN	\$75.00
1 pc	Headlamp assy - MIS	\$280.00
2 pcs	View mirror L/R \$ \$45 - cut	\$90.00
1 set	Front side cowling emblem L/R X NN	\$58.00
2 pcs	Front fork tube assy L/R @ \$90 - BT	\$180.00
2 pcs	Front fork tube guard L/R @ \$40 X NN	\$80.00
1 pc	Front lower steering stem - BT	\$230.00
1 pc	Front wheel rim X NN	\$290.00
1 pc	Front brake disc X NN	\$250.00
1 pc	Front fender / CRA	\$90.00
1 pc	Front footrest LH PH X NN	\$20.00
1 pc	Front footrest bracket RH - BR	\$55.00
1 pc	Rear footrest RH X NN	\$20.00
1 pc	Rear footrest bracket RH X NN	\$55.00
1 pc	Middle/rear cowling LH - cut	\$120.00
1 pc	Exhaust cover/protector - cut	\$70.00
		\$2,873.00
	Less 10%	\$287.30
		\$2,585.70

S/NETT ITEM

1 set	Front rim bearing & oil seal X NN	\$55.00
1 set	Steering cone upper/lower bearing - dec.	\$68.00
1 pc	Front number sticker - dec	\$20.00
1 pc	Body cowling sticker - dec	\$80.00
2 pcs	Fork oil seal & duct cover L/R @ \$38.00 - } dec	\$76.00
2 bots	Fork oil @ \$15.00 /	\$30.00
		\$2,914.70

Labour charge

1]	Towing service charge. (2 Trips)	\$80.00 ?
2]	Spray painting	\$450.00 X NN
3]	Front body frame alignment.	\$380.00 ?
4]	Replace, realign & adjust above damaged parts. check wiring, re-connection & lighting system.	\$450.00 200

Sub Total: \$1,360.00

3 Days.
 Impam repair.
 After repair photos.
 Guo Qiang - 82880282
 01/10/2020

Total Parts and Labour \$4,274.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: