



TRANS EUROKARS PTE LTD


EUROKARS GROUP

ESTIMATE COST OF REPAIRS

EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block MND Complex, Singapore 069110 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Koh Kim Hua Michael ADDRESS : No,69 Jalan Chengkek Singapore 369292 TEL : 81136754		WIP : 33975 EXCESS : DATE: 19-Aug-20 <i>04 SEP 14:30 TR</i> <i>09 SEP 13:30</i>	
VEH NO :	SKV7029B	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6CW1071G0122423	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 5	DATE REG.:	29-Sep-15	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	FRONT BUMPER	1	MC513-50-031BBB	<i>12</i>	\$ 1,108.20
2	BRACKET LHS, FRONT BUMPER	1	MC513-50-161B	<i>11</i>	\$ 41.90
3	GROMMET, FRONT BUMPER	1	MC513-50-0U5A	<i>12</i>	\$ 16.20
4	GROMMET, FRONT BUMPER	1	MC513-50-0T5A	<i>12</i>	\$ 16.20
5	RIVET, FRONT BUMPER	4	MBN8F-50-355	<i>12</i>	\$ 22.80
6	RIVET, FRONT BUMPER	4	MEA01-50-037	<i>12</i>	\$ 32.00
7	COVER LHS, FOGLAMP	1	MC513-50-C21	<i>11</i>	\$ 78.20
8	RIVET, GRILLE	3	MS51S-51-833	<i>11</i>	\$ 12.00
9	FRONT FENDER LHS	1	MCG37-52-211	<i>DD</i>	\$ 322.40
10	STAY LHS,FRONT FENDER	1	MC513-52-240	<i>12</i>	\$ 30.60
11	MUDGUARD LHS	1	MC513-56-140B	<i>11</i>	\$ 216.30
12	FASTENER, MUDGUARD	15	MB45A-56-146A	<i>11</i>	\$ 45.00
13	HEADLAMP LHS	1	MC513-51-0L0F	<i>520</i>	\$ 1,482.00
14	CLIP, HEADLAMP	3	MDR61-50-133	<i>12</i>	\$ 19.50
15	RIVET, HEADLAMP	1	MB092-51-833	<i>12</i>	\$ 3.50
17	BULB	2	M9070-37-550	<i>11</i>	\$ 100.00
19	BULB, HEAD LAMP	2	M9970-37-650	<i>11</i>	\$ 100.00
20	BULB, YELLOW	2	M11-9970-13-210Y	<i>11</i>	\$ 7.80
21	BULB	2	M11-9970-16-050	<i>11</i>	\$ 6.00
TOTAL PARTS					\$ 3,660.60
TOTAL PARTS COST					\$ 3,660.60
Labour Description					
1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER LH. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. <i>660</i>		<i>990</i>	\$ 1,650.00

2	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER, BONNET AND FRONT FENDER LH.	945	\$ 2,205.00
3	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
16	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	11X	\$ 250.00
17	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
19	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 100.00
			20	
TOTAL LABOUR			\$ -	\$ 4,805.00
TOTAL PARTS			\$ -	\$ 3,660.60
TOTAL			\$ -	\$ 8,465.60
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ -	
GST 7%			\$ -	\$ -
GRAND TOTAL			\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorised
LKK
3 Days.
The photo before repair.
9/9/20

P/P \$ 4200.20