

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20009323/AQF3N2**Date:** 24/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00004272000
Claimant Vehicle No :	SBQ9927D	Insured Vehicle No :	SLE2371Y
Date of Loss:	29/08/2020	Nature of Claim:	TP
		Claim No:	SNM20D203135C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBQ9927D	Engine No:	10296322031190
Make & Model:	MERCEDES-BENZ 200E, 2.0 (A)	Chassis No:	WDB1240212B516117
Reg. Date:	08/08/1991 (Man. Year: 1991)	Odometer:	197888 km
Colour:	Blue		
Engine Capacity:	1996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65R15	Rear Tyre Size:	205/65R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,793.00	10,898.60	5,894.40	35.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,870.00	3,670.00	1,200.00	24.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,663.00	14,568.60	7,094.40	32.75
Approved Total (Overridden) (\$\$)		11,000.00		
Nett Amount (\$\$)	21,663.00	11,000.00	10,663.00	49.22

INSPECTION

Date of Assignment:	01/09/2020	Best Solution Autocare Pte Ltd (HQ) 53 UBI AVE 1 #03-01 PAYA UBI INDUSTRIAL PARK Singapore 408934
Date Inspected:	02/09/2020 Inspected At:	
Estimated Period of Repair:	12.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2022)
Parts:	143	MERCEDES-BENZ 200E 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBQ9927D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,345.00 F	*1,345.00 FL
2	1		*REAR BUMPER PAD	Distorted	365.00 F	*365.00 FL
3	1		*REAR BUMPER CHROME MOULDING	Damaged	364.00 F	*364.00 FL
4	1		*TAILLAMP	O/s Smashed	878.00 F	*439.00 FL
5	1		*TAILLAMP PANEL RH	Distorted	98.00 F	*98.00 FL
6	1		*BOOTLID	Distorted	1,545.00 F	*1,545.00 FL
7	1		*BOOTLID LOCK	Jammed	268.00 F	*268.00 FL
8	1		*BOOTLID WEATHERSTRIPE	Cut	205.00 F	*205.00 FL
9	2		*BOOTLID HINGE	Bent	216.00 F	*216.00 FL
10	1		*BOOTLID OUTER CHROME MOULDING	Cracked	179.00 F	*179.00 FL
11	1		*MERCEDES BENZ LOGO	Necessary	58.00 F	*58.00 FL
12	1		*E200 EMBLEM	Necessary	69.00 F	*69.00 FL
13	1		*REAR END PANEL	Distorted	657.00 F	*657.00 FL
14	1		*REAR END PANEL TOP GARNISH	Deformed	185.00 F	*185.00 FL
15	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	299.00 F	*- FL
16	1		*REAR RH FENDER	Distorted	1,085.00 F	*1,085.00 FL
17	1		*REAR RH FENDER INNER TRIM	Crumpled	289.00 F	*289.00 FL
18	1		*REAR RH FENDER AIR VENT	Not Necessary	58.00 F	*- FL
19	1		*REAR RH FENDER WHEEL HOUSE PANEL	Repair	985.00 F	*- FL
20	1		*REAR WINDSCREEN	Shattered	1,067.00 F	*1,067.00 FL
21	1		*REAR WINDSCREEN MOULDING	Necessary	245.00 F	*245.00 FL
22	1		*SPEAKER PANEL TRIM BOARD	Stained	505.00 F	*505.00 FL
23	1		*REAR RH DOOR	Repair	1,386.00 F	*- FL
24	1		*REAR RH DOOR LOCK	Not Necessary	356.00 F	*- FL
25	1		*REAR RH DOOR WEATHERSTRIPE	Not Necessary	258.00 F	*- FL
26	1		*FRONT RH DOOR	Buckled	1,455.00 F	*1,455.00 FL
27	1		*FRONT RH DOOR LOCK	Not Necessary	368.00 F	*- FL
28	1		*FRONT RH DOOR WEATHERSTRIPE	Necessary	265.00 F	*265.00 FL
29	1		*FRONT RH DOOR LOWER PROTECTOR	Damaged	385.00 F	*385.00 FL
30	1		*FRONT RH DOOR GLASS OUTER MOULDING	Bent	165.00 F	*165.00 FL
31	1		*REAR RH FENDER INNER TRIM CLIPS	Necessary	30.00 FS	*30.00 FS
32	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
33	1		*REAR RH WHEEL RIM	Cut	800.00 FS	*500.00 FS
34	1		*REAR RH TYRE	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,793.00	12,044.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	1,145.40
Total Parts (\$)	16,793.00	10,898.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	1,600.00
2	SPRAY PAINTING	New	1,800.00	1,400.00
3	WIRING	New	100.00	30.00
4	TO REMOVE UPHOLSTERY	New	150.00	80.00
5	TO REPLACE REAR WINDSCREEN	New	180.00	120.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
7	TO TRANSFER FRONT AND REAR DOOR FITTINGS	New	300.00	80.00
8	TO REMOVE FUEL TANK	New	150.00	80.00
9	TO VACCUM AND CLEAN UP GLASS SHARDS	New	120.00	80.00
10	TOWING FEES *KING ROLLER)	New	120.00	120.00
Gross Labour Cost (\$\$)			4,870.00	3,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >