

SBC9927D. 1991 August.

Date

No

Mercedes Benz 200E. 1996cc

WDB124Q12BS16117

Rear Bumper. Distorted	1345	✓
Rear Bumper Pad. Distorted	365	✓
Rear Bumper Chrome Moulding Damaged	364	✓
Taillamp x02 RH smashed	439x2 = 878	439.
Taillamp Panel RH. Distorted	98	✓
Bootlid Distorted	1545	✓
Bootlid Lock Jammed.	268	✓
Bootlid Weatherstripe. Cut	205	✓
Bootlid Hinge x02 Bent	108x2 = 216	✓
Bootlid Outer Chrome Moulding. Cracked	179.	✓
Mercedes Benz Logo. } Nec	58.	✓
E200 Emblem.	69	✓
Bootlid Lower Apron Panel.	=	
Rear End Panel Distorted	657	✓
Rear End Panel Top Garnish. Dehd	185	✓
Spare Tyre Panel Top Cover. Not Nec	299	X
Rear RH Fender Distorted	1085	✓
Rear RH Fender Inner Trim. Crumpled	289	✓
Rear RH Fender Inner Trim Clips. New	30(SN)	✓
Rear RH Fender Air Vent Not Nec	58.	X
Rear RH Fender Wheel House Panel. Repair	985	X
Rear Windscreen Shattered	1067	✓
Rear Windscreen Moulding. } Nec	345	✓
Rear Windscreen Sealant.	60(SN)	✓
Speaker Panel Trim Board. Stained	505	✓
Rear RH Wheel Rim. Cut	800(SN)	500(SN).
Rear RH Tyre. Not nec	300(SN)	X
Rear RH Door Repair	1386	X
Rear RH Door Lock Not Nec	356	X
Rear RH Door Weatherstripe Not Nec	258	X
Front RH Door Buckled	1455	✓
Front RH Door Lock Not nec	368	X

SB09927D

Date: No.

Front RH Door Weatherstripe New 265 ✓
 Front RH Door Lower Protector Dunc 385 ✓
 Front RH Door G(4) Outer Moulding Bert 165 ✓

11454
 10308.60

S/N: 530

Panel Beating
 Spray Painting
 Wiring.

3670

1800 1600

1800 1400

100 30

150 80

180 120

150 80

300 80

150 80

120 80

120 ✓

To remove upholstery
 To replace rear windscreen
 To perform wheel alignment
 To transfer front and rear door fittings
 To remove fuel tank
 To vacuum and clean up glass shards
 Towing Fees (King Roller)

Total: 14508.60

H/S: 11k (Nett Value)

12 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: