

ASS. REC. BY:

REF:

A61 200093351Kc

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S14D 5932L

Yr Regn:

01, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

M.P. white / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

137053

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU603078814

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Pailun

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

31/8/20

D.O.I.

1/9/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/ GIA not ready, Got BI

14/9 @ 1805-25 call

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Not Authored
Reserve B4 paint

01805-25

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5932L

AAD2008-133

Vehicle No.:

Chassis No.:

Vehicle Make:

01 SEP 2020

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 5932L

JTDKB3FU603078814

TOYOTA

PRIUS

31.8.2020

AIG

11/1/2019

PART	
1	REAR BUMPER
1	REAR BUMPER REINFORCEMENT
1	REAR BUMPER TOWING COVER
1	GUARD, REAR BUMPER, CENTER
1	REAR BUMPER SIDE RETAINER RH
1	REAR TAILGATE OUTER GARNISH
1	REAR TAILGATE WEATHERSTRIP
1	PANEL SUB-ASSY, BODY LOWER BACK
1	TAILLAMP LOWER RH
1	TAILLAMP UPPER RH
1	REAR BUMPER SIDE RH
1	REAR BUMPER SIDE LH
1	COVER, FLOOR UNDER, NO.1
1	COVER, REAR FLOOR
1	REAR COMBINATION LAMP COVER

LIST	
\$	Bu 442.60 ✓
\$	BT 332.70 ✓
\$	nd 15.40 ✓
\$	Rd/CW 576.30 ✓
\$	SL 117.70
\$	SL 925.60
\$	SL 372.30
\$	R 650.30
\$	SL 502.00
\$	SL 451.80
\$	SL 123.70
\$	SL 123.70
\$	SL 175.10
\$	SL 229.90
\$	SL 64.50
TOTAL \$ 5,103.60	
25% \$ 1,275.90	
\$ 3,827.70	

Special Nett

1SET	PARKING AID
1SET	REAR BUMPER CLIP
1	REAR TAILGATE TOYOTA LOGO
1	REAR TAILGATE WORDING 'PRIUS'
1	REAR TAILGATE WORDING 'HYBRID'
1	REAR TAILGATE STICKER 'TRANS-CAB'

\$	Short 700.00 2205M ✓
\$	SL 75.00 ✓
\$	na 47.00 X
\$	na 52.90 X
\$	na 53.50 X
\$	na 80.00 X

Trans-cab Auto Services Pte Ltd

AAD2008-133

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5932L

1 REAR TAILGATE STICKER '6555-3333'	\$	nn	80.00	} X
1 REAR BUMPER PROTECTOR	\$	nn	180.00	
1 REAR BUMPER RETAINER CLIP	\$	nn	65.00	
1SET TAILLAMP LOWER CLIP	\$	nn	40.00	
1SET TAILLAMP UPPER CLIP	\$	nn	40.00	
1 Rear Licence Plate with Holder	\$	nn	130.00	
TOTAL	\$		1,543.40	

TOTAL PARTS	\$	5,371.10
--------------------	-----------	-----------------

LABOUR

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,200.00	2200
To reinstall rear bumper parking sensor.	\$		170.00	500
To Check Electrical Lighting Concerned.	\$		170.00	150
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,200.00	2000
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	250.00	X
TOTAL	\$		3,370.00	
Over All Total	\$		8,741.10	

(PART-BY-PART) Repair Days15 Days
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5932L

AAD2008-133

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHD5932L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	31 Aug 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B94959
Chassis No.:	JTDKB3FU603078814
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	11 Jan 2019
First Registration Date:	11 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jan 2027
PARF Rebate Amount:	\$10,685.00

Intended COE Rebate Details

COE Expiry Date:	10 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$20,838.00
COE Rebate Amount:	\$16,566.00
Total Rebate Amount:	\$27,251.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 31 Aug 2020

OK