

Not Authoised
Reservy B4 paint
@ 1805-25

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5932L

AAD2008-133

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

01 SEP 2020

SHD 5932L

JTDKB3FU603078814

TOYOTA

PRIUS

31.8.2020

AIG

11/1/2019

PART	
1	REAR BUMPER
1	REAR BUMPER REINFORCEMENT
1	REAR BUMPER TOWING COVER
1	GUARD, REAR BUMPER, CENTER
1	REAR BUMPER SIDE RETAINER RH
1	REAR TAILGATE OUTER GARNISH
1	REAR TAILGATE WEATHERSTRIP
1	PANEL SUB-ASSY, BODY LOWER BACK
1	TAILLAMP LOWER RH
1	TAILLAMP UPPER RH
1	REAR BUMPER SIDE RH
1	REAR BUMPER SIDE LH
1	COVER, FLOOR UNDER, NO.1
1	COVER, REAR FLOOR
1	REAR COMBINATION LAMP COVER

LIST	
\$	Bu 442.60 ✓
\$	BT 332.70 ✓
\$	nd 15.40 ✓
\$	rd/lt 576.30 ✓
\$	SL 117.70
\$	SL 925.60
\$	SL 372.30
\$	R 650.30
\$	SL 502.00
\$	SL 451.80
\$	SL 123.70
\$	SL 123.70
\$	SL 175.10
\$	SL 229.90
\$	SL 64.50
TOTAL	\$ 5,103.60
25%	\$ 1,275.90
	\$ 3,827.70

Special Nett

1SET	PARKING AID	\$	Short 700.00	220SN ✓
1SET	REAR BUMPER CLIP	\$	na 75.00	✓
1	REAR TAILGATE TOYOTA LOGO	\$	na 47.00	X
1	REAR TAILGATE WORDING 'PRIUS'	\$	na 52.90	X
1	REAR TAILGATE WORDING 'HYBRID'	\$	na 53.50	X
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	na 80.00	X

Trans-cab Auto Services Pte Ltd

AAD2008-133

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5932L

1 REAR TAILGATE STICKER '6555-3333'	\$	<i>nn</i> 80.00	} X
1 REAR BUMPER PROTECTOR	\$	<i>nn</i> 180.00	
1 REAR BUMPER RETAINER CLIP	\$	<i>nn</i> 65.00	
1SET TAILLAMP LOWER CLIP	\$	<i>nn</i> 40.00	
1SET TAILLAMP UPPER CLIP	\$	<i>nn</i> 40.00	
1 Rear Licence Plate with Holder	\$	<i>nn</i> 130.00	
TOTAL	\$	1,543.40	

TOTAL PARTS \$ 5,371.10**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,200.00 *2201*

To reinstall rear bumper parking sensor.

\$ 170.00 *501*

To Check Electrical Lighting Concerned.

\$ 170.00 *151*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,200.00 *2001*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 250.00 X

TOTAL \$ 3,370.00**Over All Total \$ 8,741.10****(PART-BY-PART) Repair Days**

~~15 Days~~
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: