

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/III20009338/KGA3Q2  
**Date:** 20/05/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b>	SHF592G	<b>Insured Vehicle No :</b>	SH6011L
Date of Loss:	29/08/2020	Nature of Claim:	TP
		Claim No:	MCT20080501

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHF592G</b>		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C001422
Reg. Date:	20/06/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC278431
Colour:	Metallic White/Red	Odometer:	590785 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,754.61	445.71	11,308.90	96.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,270.00	310.00	3,960.00	92.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,024.61</b>	<b>755.71</b>	<b>15,268.90</b>	<b>95.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>600.00</b>		

(S\$)	16,024.61	600.00	15,424.61	96.26
<b>+ GST 7.00/7.00% (S\$)</b>	1,121.72	42.00	1,079.72	96.26
<b>Nett Amount (S\$)</b>	<b>17,146.33</b>	<b>642.00</b>	<b>16,504.33</b>	<b>96.26</b>
<b>+ Car Rental (2.5 x S\$95.04/day) (S\$)</b>		237.60		
<b>Nett Liability (S\$)</b>		<b>879.60</b>		

INSPECTION

Date of Assignment: 01/09/2020

Date Inspected: 01/09/2020

Estimated Period of Repair: 1.5 days

Inspected At: Trans-cab Auto Services Pte Ltd  
No 2 Ang Mo Kio Street 63  
Singapore 569111

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 19 Nov 2020)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHF592G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Repair	561.70 FL	*- FL
2	1		*BUMPER LOWER REAR	Dented / Cut	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
5	1		*BUMPER REFLECTOR REAR	Serviceable	16.60 FL	*- FL
6	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
7	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
8	1		*BUMPER BEAM REAR	Repair	547.80 FL	*- FL
9	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*- FL
10	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
11	1		*TAIL LAMP	Serviceable	401.40 FL	*- FL
12	1		*BOOT REAR	Repair	1,677.20 FL	*- FL
13	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL
14	1		*BOOT REFLECTOR LAMP	Serviceable	277.70 FL	*- FL
15	1		*BOOT BADGE RENAULT	Not Necessary	82.40 FL	*- FL
16	1		*BOOT BADGE	Not Necessary	95.80 FL	*- FL
17	1		*BOOT HINGE	Repair	254.20 FL	*- FL
18	1		*EXHAUST REAR	Repair	5,263.60 FL	*- FL
19	1		*EXHAUST CAP REAR	Repair	125.40 FL	*- FL
20	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
21	1		*SET REAR BUMPER CLIP	Not Necessary	75.00 FS	*- FS
22	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	65.00 FS	*- FS
23	1		*SET BUMPER RETAINER CLIP RR	Not Necessary	60.00 FS	*- FS
24	1		*SET BUMPER BRACKET SIDE CLIP RR	Not Necessary	65.00 FS	*- FS
25	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	70.00 FS	*- FS
26	1		*SET BUMPER LOWER REAR CLIP	Necessary	75.00 FS	*75.00 FS
27	1		*BOOT STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*BOOT STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
29	1		*TAILLAMP CLIP	Not Necessary	40.00 FS	*- FS
30	1		*REAR BUMPER PROTECTOR	Not Necessary	180.00 FS	*- FS
31	1		*SET END PANEL TRIM CLIP	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,888.46</b>	<b>486.90</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,133.85	41.19
<b>Total Parts (\$\$)</b>	<b>11,754.61</b>	<b>445.71</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,200.00	80.00
2	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
5	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	220.00
7	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
8	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
9	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
10	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>4,270.00</b>	<b>310.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >