

Not Authorised
L/Rng & 600/

AAD2008-130

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 592G

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

01 SEP 2020

SHF 592G

VF1ABL15AUC278431

RENAULT

LATITUDE

29.8.2020

III

20/6/2014

	PART
1	BUMPER COVER REAR
1	BUMPER LOWER REAR
1	BUMPER BRACKET CTR REAR
1	BUMPER RETAINER RH REAR
1	BUMPER REFLECTOR REAR
1	BUMPER BRACKET SIDE RH REAR
1	BUMPER RETAINER LH REAR
1	BUMPER BEAM REAR
1	OUTER PANEL REAR (End Panel)
1	OUTER PANEL REAR (End Panel) TRIM
1	TAIL-LAMP
1	BOOT REAR
1	BOOT WEATHERSTRIP
1	BOOT REFLECTOR LAMP
1	BOOT BADGE 'RENAULT'
1	BOOT BADGE
1	BOOT HINGE
1	EXHAUST REAR
1	EXHAUST CAP REAR

	LIST	
\$	R	561.70 X
\$	Od/Lm	411.90
\$	R	98.10
\$	R	59.80
\$	R	16.60
\$	R	82.10
\$	R	54.20
\$	R	547.80
\$	R	745.80
\$	R	404.56
\$	R	401.40
\$	R	1,677.20
\$	R	178.20
\$	R	277.70
\$	R	82.40
\$	R	95.80
\$	R	254.20
\$	R	5,263.60
\$	R	125.40
TOTAL	\$	11,338.46
10%	\$	1,133.85
	\$	10,204.61

Special Nett

1SET PARKING AID

1SET REAR BUMPER CLIP

\$	R	700.00 X
\$	R	75.00 X

Trans-cab Auto Services Pte Ltd

AAD2008-130

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 592G

1SET BUMPER BRACKET CTR CLIP	\$	na	65.00	X
1SET BUMPER RETAINER CLIP RR	\$	na	60.00	X
1SET BUMPER BRACKET SIDE CLIP RR	\$	na	65.00	X
1SET BUMPER LOWER REAR RIVET	\$	na	70.00	X
1SET BUMPER LOWER REAR CLIP	\$	na	75.00	✓
1 BOOT STICKER "Trans-cab"	\$	na	80.00	X
1 BOOT STICKER "6555-3333"	\$	na	80.00	X
1 TAILLAMP CLIP	\$	na	40.00	X
1 Rear Bumper Protector	\$	na	180.00	X
1SET END PANEL TRIM CLIP	\$	na	60.00	X
TOTAL	\$		1,550.00	
TOTAL PARTS	\$		11,754.61	

LABOUR

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$ 1,200.00 801

To Rust-Proofing and apply undercoat Of The Affected
Areas.

\$ na 250.00 X

To remove and refit interior fittings, trimings, garnish,
fittings and other, to enable repair.

\$ 380.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 101

To drop rear exhaust box, renew the same, to repair
and realign centre exhaust pipe.

\$ 170.00 X

Putty and spray painting of the affected portion.

\$ 1,200.00 2201

To transfer of rear bumper fittings, attachment and
perform water seepage test.

\$ 170.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 592G**AAD2008-130**

To reinstall rear bumper parking sensor.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
TOTAL	\$	4,270.00	

Over All Total \$ 16,024.61**LUMP SUM (REPAIR DAY)****20 DAYS**
*1 1/2 days***For Official Use**Prepared By : _____
(Accident Dept)Verify By : _____
(Accident Workshop)Checked By : _____
(Finance Dept)LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: