

Not Authorised
L/Rng & 600/

Trans-cab Auto Services Pte Ltd

AAD2008-130

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 592G

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

01 SEP 2020

SHF 592G

VF1ABL15AUC278431

RENAULT

LATITUDE

29.8.2020

III

20/6/2014

PART	
1	BUMPER COVER REAR
1	BUMPER LOWER REAR
1	BUMPER BRACKET CTR REAR
1	BUMPER RETAINER RH REAR
1	BUMPER REFLECTOR REAR
1	BUMPER BRACKET SIDE RH REAR
1	BUMPER RETAINER LH REAR
1	BUMPER BEAM REAR
1	OUTER PANEL REAR (End Panel)
1	OUTER PANEL REAR (End Panel) TRIM
1	TAIL-LAMP
1	BOOT REAR
1	BOOT WEATHERSTRIP
1	BOOT REFLECTOR LAMP
1	BOOT BADGE 'RENAULT'
1	BOOT BADGE
1	BOOT HINGE
1	EXHAUST REAR
1	EXHAUST CAP REAR

LIST	
\$	R 561.70 X
\$	Od/16 411.90
\$	R 98.10
\$	R 59.80
\$	R 16.60
\$	R 82.10
\$	R 54.20
\$	R 547.80
\$	R 745.80
\$	R 404.56 X
\$	R 401.40
\$	R 1,677.20
\$	R 178.20
\$	R 277.70
\$	R 82.40
\$	R 95.80
\$	R 254.20
\$	R 5,263.60
\$	R 125.40
TOTAL	\$ 11,338.46
10%	\$ 1,133.85
	\$ 10,204.61

Special Nett

1SET PARKING AID	\$	R 700.00 X
1SET REAR BUMPER CLIP	\$	R 75.00 X

Trans-cab Auto Services Pte Ltd**AAD2008-130**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 592G

1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i>	65.00	X
1SET BUMPER RETAINER CLIP RR	\$	<i>na</i>	60.00	X
1SET BUMPER BRACKET SIDE CLIP RR	\$	<i>na</i>	65.00	X
1SET BUMPER LOWER REAR RIVET	\$	<i>na</i>	70.00	X
1SET BUMPER LOWER REAR CLIP	\$	<i>na</i>	75.00	✓
1 BOOT STICKER "Trans-cab"	\$	<i>na</i>	80.00	X
1 BOOT STICKER "6555-3333"	\$	<i>na</i>	80.00	X
1 TAILLAMP CLIP	\$	<i>na</i>	40.00	X
1 Rear Bumper Protector	\$	<i>na</i>	180.00	X
1SET END PANEL TRIM CLIP	\$	<i>na</i>	60.00	X
TOTAL	\$		1,550.00	

TOTAL PARTS	\$	11,754.61
--------------------	-----------	------------------

LABOUR

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$	1,200.00	<i>801</i>
----	----------	------------

To Rust-Proofing and apply undercoat Of The Affected
Areas.

\$	<i>na</i>	250.00	X
----	-----------	--------	---

To remove and refit interior fittings, trimings, garnish,
fittings and other, to enable repair.

\$	<i>4</i>	380.00	X
----	----------	--------	---

To Check Electrical Lighting Concerned.

\$		170.00	<i>101</i>
----	--	--------	------------

To drop rear exhaust box, renew the same, to repair
and realign centre exhaust pipe.

\$	<i>4</i>	170.00	X
----	----------	--------	---

Putty and spray painting of the affected portion.

\$		1,200.00	<i>2201</i>
----	--	----------	-------------

To transfer of rear bumper fittings, attachment and
perform water seepage test.

\$	<i>4</i>	170.00	X
----	----------	--------	---

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 592G**AAD2008-130**

To reinstall rear bumper parking sensor.	\$	<i>no</i> 170.00	<i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>4</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>4</i> 220.00	<i>X</i>
TOTAL	\$	4,270.00	
Over All Total	\$	16,024.61	

LUMP SUM (REPAIR DAY)~~20 DAYS~~*1 1/2 days***For Official Use**

Prepared By :	_____
	(Accident Dept)
Verify By :	_____
	(Accident Workshop)
Checked By :	_____
	(Finance Dept)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____