

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TP mslg Denise.

SULAIMI BIN SUIB

BLK 263 TAMPINES ST 21

#02-132

S 520263

Vehicle No :SJK 4410 Y

Make/Model :MAZDA 5

Accident date :01.09.2020

JM6CR10f280307672

No	DESCRIPTION	Qty	Amount (\$S)
<u>List Items</u>			
1	Rear LH door black sticker (1 set) <i>Nec</i>	1	\$ 113.30 ✓
2	Rear LH door <i>Distorted</i>	1	\$ 1072.50 ✓
3	Rear LH door glass outer moulding <i>Deformed</i>	1	\$ 117.70 ✓
4	Rear LH door protector <i>Deformed</i>	1	\$ 86.90 ✓
5	Rear LH door outer handle <i>Damaged</i>	1	\$ 167.20 ✓
6	Rear LH door top hinge <i>Not in</i>	1	\$ 71.50 +
7	Rear LH door centre hinge <i>Not in</i>	1	\$ 75.90 +
8	Rear LH door lower roller bracket <i>Not in</i>	1	\$ 74.80 +
9	Rear LH door lower roller <i>Best</i>	1	\$ 97.90 ✓
10	Rear LH door inner lock <i>Best</i>	1	\$ 327.80 ✓
11	Rear LH door inner top stopper <i>3 New</i>	1	\$ 20.90 +
12	Rear LH door inner lower stopper <i>3 New</i>	1	\$ 25.30 +
13	Rear LH door inner board <i>Cracked</i>	1	\$ 748.00 <i>628.</i>
14	Rear LH door inner weather strip <i>Not in</i>	1	\$ 163.90 ✓
15	Rear LH door power window motor <i>Not in</i>	1	\$ 215.60 +
16	Rear LH door power window regulator <i>Damaged</i>	1	\$ 169.40 ✓
17	Rear bumper <i>Deformed</i>	1	\$ 1114.30 <i>986</i>
18	Rear bumper side holder <i>Not in</i>	1	\$ 129.80 +
19	Rear LH fender <i>Repair</i>	1	\$ 869.00 +
20	Rear LH fender inner shield <i>Deformed</i>	1	\$ 31.90 ✓
21	Rear LH lower arm <i>Best</i>	1	\$ 268.60 ✓
22	Rear LH knuckle arm <i>Best</i>	1	\$ 387.20 ✓
23	Rear LH knuckle arm bearing <i>Damaged</i>	1	\$ 434.50 <i>240.90</i>
24	Rear LH shock absorber <i>Not in</i>	1	\$ 375.10 +
25	LH rocker panel <i>Repair</i>	1	\$ 306.90 +
26	LH rocker panel garnish <i>Deformed</i>	1	\$ 844.80 <i>625.</i>
		5484.20	
		4387.36	
		\$ 8138.90	
	Less 20% Disc	\$ 1627.78	
	Total	\$ 6511.12	

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

SULAIMI BIN SUIB
BLK 263 TAMPINES ST 21
#02-132
S 520263

Vehicle No :SJK 4410 Y
Make/Model :MAZDA 5
Accident date :01.09.2020

No	DESCRIPTION	Qty	Amount (\$S)
----	-------------	-----	--------------

Special Nett Items

1	Rear LH sport rim <i>ut</i>	1	\$ 800.00 <i>400</i>
2	Rear LH tyre <i>Not New</i>	1	\$ 300.00 <i>X</i>
Total			\$ 1100.00

Labour Cost

1	To check wheel alignment	\$ 100.00 <i>80</i>
2	Remove & reinstall centre door glass	\$ 150.00 <i>30</i>
3	Remove & reinstall roof lining + cushion	\$ 150.00 <i>30</i>
4	Remove & reinstall reverse sensor	\$ 150.00 <i>50</i>
5	Remove & reinstall rear LH suspension	\$ 400.00 <i>180</i>
6	Remove ,replace & repair consistent to the accident	\$ 1600.00 <i>600</i>
7	Respray painting	\$ 1500.00 <i>800</i>
8	Tuff kote	\$ 100.00 <i>50</i>
Total		\$ 4150.00

Grand Total \$ 11761.12

total: 6607.36
4/s: 5.2K
06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5.2K.
06 Days