

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit

#01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. ONG PENG HUA
BLK 527 HOUGANG AVE 6 #09-217
S 530527

Attention : Motor Claim Department

Contact : 90477671

Estimate : ES001303

Date : 31/08/2020

Vehicle Num. : SDQ 3938 M

Make/Model : TOYOTA CAMRY-2007

Chassis/Eng# : MR053BK4107018683/1AZE064827

Accident Date : 30/08/2020

Claim No. :

Reference :

Policy No. :

TP Chin.
Jaslin

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	BOOTLID <i>Distorted</i>		1,095.00 ✓ 950.
2.	1 PC	BOOTLID REFLECTOR LH <i>cracked</i>		395.00 ✓
3.	1 PC	BOOTLID REFLECTOR RH		395.00 ✓
4.	1 PC	TOYOTA EMBLEM <i>new</i>		75.00 ✓
5.	1 PC	CAMRY EMBLEM		58.00 ✓
6.	1 PC	LICENCE PLATE LAMP <i>new</i>		65.00 ✓
7.	1 PC	REAR NUMBER PLATE & BASE <i>Best</i>		60.00 ✓
8.	1 PC	REAR LAMP RH <i>cracked</i>		510.00 ✓
9.	1 PC	REAR LAMP LH		510.00 ✓
10.	1 PC	REAR FENDER RH <i>Distorted</i>		925.00 ✓
11.	1 PC	REAR FENDER LH <i>cracked</i>		925.00 ✓
12.	1 PC	REAR FENDER INNER TRIM LH <i>crumpled</i>		400.00 ✓ 250
13.	1 PC	REAR FENDER INNER TRIM RH		400.00 ✓ 250
14.	1 PC	REAR FENDER INNER SHIELD LH <i>new</i>		180.00 ✓
15.	1 PC	REAR FENDER INNER SHIELD RH <i>torn</i>		180.00 ✓
16.	1 PC	REAR BUMPER <i>Distorted</i>		785.00 ✓ 585
17.	1 PC	REAR BUMPER REINFORCEMENT <i>Best</i>		395.00 ✓ 285
18.	1 PC	REAR BUMPER BRACKET LH <i>new</i>		60.00 ✓
19.	1 PC	REAR BUMPER BRACKET RH <i>new</i>		60.00 ✓
20.	1 PC	REAR BUMPER RETAINER LH <i>new</i>		60.00 ✓
21.	1 PC	REAR BUMPER RETAINER RH <i>new</i>		60.00 ✓
22.	10 PCS	REAR BUMPER CLIP <i>new</i>	4.00	40.00 ✓
23.	1 PC	REAR BUMPER SPONGE <i>new</i>		200.50 ✓
24.	1 PC	REAR BUMPER REFLECTOR LH <i>new</i>		65.00 ✓

CONTINUE / ...

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit

#01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. ONG PENG HUA
BLK 527 HOUGANG AVE 6 #09-217
S 530527

Attention : Motor Claim Department

Contact : 90477671

Estimate : ES001303

Date : 31/08/2020

Vehicle Num. : SDQ 3938 M

Make/Model : TOYOTA CAMRY-2007

Chassis/Eng# : MR053BK4107018683/1AZE064827

Accident Date : 30/08/2020

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1 PC	REAR BUMPER REFLECTOR RH <i>cracked.</i>		65.00 ✓
26.	1 PC	REAR END PANEL <i>Distorted</i>		755.00 ✓
27.	1 PC	REAR END PANEL INNER <i>new</i>		455.00 x
28.	1 PC	REAR END PANEL GARNISH <i>Distorted</i>		400.00 <i>255</i>
29.	2 PCS	REAR END PANEL GARNISH CLIPS <i>new</i>	4.00	8.00 ✓
30.	1 PC	BOOTLID WEATHERSTRIP <i>cut</i>		225.00 ✓
31.	2 PCS	BOOTLID WEATHERSTRIP CLIP <i>new</i>	4.00	8.00 x
32.	1 PC	SPARE TYRE COMPARTMENT <i>Distorted</i>		780.00 ✓
33.	1 PC	SPARE TYRE BOARD <i>torn</i>		215.00 ✓
34.	1 PC	SPARE TYRE INSULATOR COAT <i>new</i>		255.00 ✓
35.	1 PC	REAR CHASSIS MEMBER LH <i>Repair</i>		985.00 x
36.	1 PC	REAR CHASSIS MEMBER RH <i>Repair</i>		985.00 x
37.	1 PC	BOOTLID HINGES LH <i>Best</i>		153.00 ✓
38.	1 PC	BOOTLID HINGES RH <i>Best</i>		153.00 ✓
39.	1 PC	BOOTLID CABLE <i>Jammed</i>		85.00 ✓
40.	1 PC	BOOTLID LOWER LOCK <i>Best</i>		85.00 ✓
41.	1 PC	BOOTLID LOCK <i>Jammed</i>		380.00 ✓
42.	1 PC	REAR WINDSCREEN <i>cut</i>		780.00 ✓
43.	1 PC	REAR WINDSCREEN MOULDING <i>new</i>		95.00 ✓
44.	1 PC	REAR SHOCK ABSORBER LH <i>new</i>		465.00 x
45.	1 PC	REAR SHOCK ABSORBER RH <i>new</i>		465.00 x
46.	1 PC	REAR SHOCK ABSORBER MOUNTING LH <i>new</i>		275.00 x
47.	1 PC	REAR SHOCK ABSORBER MOUNTING RH <i>new</i>		275.00 x
48.	1 PC	REAR TRAILING ARM LH <i>new</i>		285.00 x
49.	1 PC	REAR TRAILING ARM RH <i>new</i>		285.00 x
50.	1 PC	REAR LOWER ARM LH <i>new</i>		255.00 x

CONTINUE / ...

LEE SHENG AUTO PTE LTD

Page 3 / 4

1, Kaki Bukit Ave 6, Autobay@KakiBukit
#01-60/58, Singapore 417883
Tel No. : 67477333 Fax No. : 67457138
E-Mail : leesheng@singnet.com.sg
Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. ONG PENG HUA
BLK 527 HOUGANG AVE 6 #09-217
S 530527

Attention : Motor Claim Department
Contact : 90477671

Estimate : ES001303

Date : 31/08/2020
Vehicle Num. : SDQ 3938 M
Make/Model : TOYOTA CAMRY-2007
Chassis/Eng# : MR053BK4107018683/1AZE064827
Accident Date : 30/08/2020
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
51.	1 PC	REAR LOWER ARM RH		255.00 X
52.	1 PC	REAR CROSS MEMBER		255.00 X
53.	1 PC	REAR UPPER ARM LH		385.00 X
54.	1 PC	REAR UPPER ARM BUSH RH		56.00 X
55.	1 PC	REAR STABILISER BAR		385.00 X
56.	1 PC	REAR KNUCKLE ARM RH		595.00 X
57.	1 PC	REAR KNUCKLE ARM LH		595.00 X
58.	1 PC	REAR EXHAUST ASSY		990.00 X
59.	1 PC	REAR EXHAUST PIPE		930.00 X
		List Total S\$:		21,516.50
		25.00% Discount S\$:		5,379.13
				16,137.37
1.	1 PC	SPECIAL NETT ITEMS : REAR BUMPER SPOILER		500.00 ✓
2.	2 PCS	REAR WINDSCREEN GLUM	60.00	120.00 ✓
		Special Nett Total S\$:		620.00
		LABOUR :		
		REMOVE & REFIX WINDSCREEN		120.00 ✓
		REMOVE & REFIX CUSHION		80.00 ✓
		REMOVE & REFIX FUEL TANK		180.00 ✓
		REMOVE & REFIX UNDERCARRIAGE		400.00 X

CONTINUE / ...

LEE SHENG AUTO PTE LTD

Page 4 / 4

1, Kaki Bukit Ave 6, Autobay@KakiBukit
#01-60/58, Singapore 417883
Tel No. : 67477333 Fax No. : 67457138
E-Mail : leesheng@singnet.com.sg
Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. ONG PENG HUA
BLK 527 HOUGANG AVE 6 #09-217
S 530527

Attention : Motor Claim Department
Contact : 90477671

Estimate : ES001303

Date : 31/08/2020
Vehicle Num. : SDQ 3938 M
Make/Model : TOYOTA CAMRY-2007
Chassis/Eng# : MR053BK4107018683/1AZE064827
Accident Date : 30/08/2020
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE & REFIX ROOF LINING		180.00 150
		KNOCKING, JACKING, STRAIGHTEN CHASSIS ETC		2,200.00 2000
		SPRAY PAINTING ON BOOTLID, R FENDER RH/ LH, END PANEL		2,000.00 1800
		SPARE TYRE COMPARTMENT, RR DOOR LH & RH, BUMPER		
		Labour Total S\$:		5,160.00

4230
Total: 14140.25
4/5 : 7k. (Nett Value)
18 Days.

Total S\$: 21,917.37
=====

LEE SHENG AUTO PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: