

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 47554

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0624/2020/NS/NS
Date : 2-Sep-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured veh no : SLU 9850 B

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Sim Irene
Address : 3 West Coast Drive
Singapore 128021
Telephone : (HP) +65 97515530
Type of Claim : Third Party Claims
Policy No. :
Vehicle No : **SMA 874 K**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : 28/5/2018
Engine No : CHZ 907351
Chassis No : WAUZZZ8V4J1057926
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Aug-20
Place of Accident : Java Road To Nicoll Highway

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMA 874 K

S/n	Nature of Jobs	Estimated Charges	Survivor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00	/
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00	X
3	To dismantle and renew rear bumper, rear bumper spoiler and rear lid. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00	1600
4	To respray rear bumper and rear lid.	\$ 2,000.00	1100
5	To carry out diagnostic check.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 4,852.00	

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 874 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>de ✓</i>	\$ 1,944.00	
2	REAR BUMPER FIXING PARTS ?	\$ 191.00	
3	REAR BUMPER GUIDE SECTION - LH / RH ?	2 \$ 32.00	
4	REAR BUMPER LOCKING MECHANISM ?	2 \$ 59.00	
5	REAR BUMPER SPOILER <i>cut ✓</i>	\$ 234.00	
6	REAR LIGHT REFLECTOR - LH / RH X	2 \$ 82.00	
7	LED LICENSE PLATE LIGHT X	2 \$ 197.00	
8	REAR BUMPER SIDE REINFORCEMENT BEAM ?	\$ 565.00	
9	REAR BUMPER BRACKET - LH ?	\$ 27.00	
10	REAR BUMPER BRACKET - RH ?	\$ 28.00	
11	REAR BUMPER GUIDE SECTION - RH ?	\$ 66.00	
12	REAR PARKING AID SENSOR - INNER / OUTER <i>an ✓</i>	2 TBC	
13	REAR LID LOCK X	\$ 2,564.00	
14	REAR LID ATTACHMENT PARTS X	\$ 291.00	
15	REAR LID HINGE - LH / RH X	2 \$ 506.00	
16	REAR LID FLAP GASKET X	\$ 203.00	
17	REAR LID LOCK STRIKER X	\$ 49.00	
18	REAR LID LOCK X	\$ 184.00	
19	REAR LID PROTECT CAP X	\$ 16.00	
20	PACKING ADHESIVE <i>rec ✓</i>	\$ 18.00	
21	AUDI EMBLEM <i>an ✓</i>	\$ 122.00	
22	A3 INSCRIPTION <i>an ✓</i>	\$ 95.00	
23	TFSI INSCRIPTION <i>an ✓</i>	\$ 95.00	
24	REAR CROSS PANEL TRIM ?	\$ 153.00	
25	REAR NO PLATE X	S/N \$ 60.00	
26	SUNDRIES ?	\$ 250.00	
TOTAL SPARE PARTS		: \$ 8,031.00	
TOTAL LABOUR CHARGES		: \$ 4,852.00	
GRAND TOTAL		: <u>\$ 12,883.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Ram - Hp 90010068*
Surveyed Date : *03/09/2020 @ 1055*
Authorised Date :
Excess Cost : *5 days*
Liability :
Remarks : *Resurvey before paint*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant