



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

02/09/2020

TP Budget Direct.

Xiao Chen

Accident date:

Estimated repair cost for vehicle no: SMP2106C MINI COOPER S 1.6 AT ABS 10'

CHASSIS: WMWMF72020TV08195

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Dented</i>		\$1,698.00 ✓ 1185
2	1	Front Bonnet Chrome Moulding <i>cracked</i>		\$159.00 ✓
3	2	Front Bonnet Hinge <i>Not new</i>	\$110.00	\$220.00 X
4	2	Front Bonnet Shock Absorber <i>Not new</i>	\$140.00	\$280.00 X
5	1	Front Bonnet Insulator <i>Not new</i>		\$269.00 X
6	10	Front Bonnet Insulator Clip <i>Not new</i>	\$6.50	\$65.00 X
7	1	Front Bonnet Lock <i>Not new</i>		\$145.00 X
8	1	Front Bonnet Mini Logo <i>New</i>		\$95.00 ✓
9	1	Front Bonnet R/H Head Lamp Chrome Moulding <i>Dented</i>		\$105.00 ✓
10	1	Front R/H Head Lamp <i>cracked</i>		\$1,548.00 ✓
11	1	Front R/H Head Lamp Lower Bracket <i>Not new</i>		\$65.00 X
12	1	Front R/H Head Lamp Nozzle Assy <i>Not new</i>		\$195.00 X
13	1	Front Grille <i>cracked</i>		\$395.00 ✓
14	10	Front Grille Clip <i>on</i>	\$6.50	\$65.00 20
15	1	Front Grille Chrome <i>cracked</i>		\$145.00 ✓
16	1	Front Support Panel <i>cracked</i>		795.00 X
17	1	Front Bumper <i>Dented</i>		\$901.00 ✓
18	1	Front R/H Bumper Side Retainer <i>Dented</i>		\$69.00 ✓
19	1	Front R/H Bumper Fog Lamp <i>cracked</i>		\$302.00 ✓
20	1	Front Bumper Center Chrome <i>Not new</i>		\$253.00 X
21	1	Front R/H Fender <i>Dented</i>		\$694.00 ✓
22	1	Front R/H Fender Protector <i>Not</i>		\$245.00 ✓
23	1	Front R/H Fender Cowling <i>Dented</i>		\$195.00 ✓
24	10	Front R/H Fender Cowling Clip <i>on</i>	\$6.50	\$65.00 20
25	1	Front R/H Rim <i>Not</i>		\$985.00 500(SW)
26	1	Front R/H Tyre <i>Not new</i>		\$300.00 X
27	1	Front R/H Lower Arm <i>Best</i>		\$595.00 ✓

28	1	Front R/H Knuckle Arm <i>new</i>	\$795.00	X
29	1	Front R/H Knuckle Arm Bearing <i>new</i>	\$330.00	✓
30	1	Front R/H Shock Absorber <i>new</i>	\$495.00	✓
31	1	Front R/H Drive Shaft <i>new</i>	\$1,385.00	X
32	1	Front Steering Rack	\$2,455.00	X

8293 SN: 500
746370

Subtotal :- \$15,513.00

Labour charges

To remove & refit front steering rack	\$380.00	X
To remove & refit cushion & trim board	\$380.00	X
To remove & refit front undercarriage	\$280.00 220	
To check wheel alignment	\$150.00 80	
To reset computer	\$380.00	X
To check wiring	\$200.00 30	
Gum	\$100.00	X
Tuff kote	1830	\$100.00 X
Towing		\$150.00 X
Panel beating	\$1,800.00 900	
Spray painting	\$1,600.00 800	

Subtotal :- \$5,520.00

Total:- \$21,033.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


total 9793.70

L/S : 7.8K
07 Dup

(7.8K) 07 Dup



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER CHEW MOTOR DATE Sep 5, 2020 10:50:55 AM

PLATE NO SMP 2106 C

MILEAGE 130806

REFERENCE CUSTOM

MODEL MINI COOPER S

Front Wheel	SPECS				DIAGNOSIS				ADJUSTMENT			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-1.00	0.00	1.00			14.50				14.50		
PARTIAL TOE	-0.50	0.00	0.50		1.90		12.50		0.60		13.80	
SET BACK	---	---	---			-0°34"				-0°34"		
CAMBER	-1°14"	-0°30"	0°14"		-0°22"		-1°18"0°54"		-0°22"		-1°16"0°52"	
CASTER	2°30"	3°30"	4°30"		3°08"		3°06" 0°02"		3°08"		3°06" 0°02"	
KING PIN	---	---	---		11°22"		10°58" 0°24"		11°22"		10°58" 0°24"	
DRIVE ANGLE	---	---	---		11°00"		9°38"		11°00"		9°42"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel	SPECS				DIAGNOSIS				ADJUSTMENT			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	0.00	1.00	2.10			6.10				6.10		
PARTIAL TOE	0.00	0.50	1.00		4.00		2.00		4.00		2.00	
SET BACK	---	---	---			0°00"				0°00"		
CAMBER	-2°14"	-1°30"	-0°44"		-1°48"		-2°10" 0°22"		-1°48"		-2°10" 0°22"	
THRUST ANGLE	-0°08"	0.00	0°08"			0°08"				0°08"		