

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/III20009349/APA3Q2

**Date:** 03/11/2020

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MPC0001205_01
<b>Claimant Vehicle No :</b>	SJB1515X	<b>Insured Vehicle No :</b>	SDB1862P
Date of Loss:	30/08/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0001732

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJB1515X</b>		
Make & Model:	BMW 316I, 1.6 AT D/AB 4DR ABS HID (A)	Engine No:	A576J742N13B16A
Reg. Date:	26/08/2014 (Man. Year: 2014)	Chassis No:	WBA3A16010NS37779
Colour:	Yellow	Odometer:	92742 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/30 R20	Rear Tyre Size:	245/30 R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,512.95	4,696.00	5,816.95	55.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	680.00	720.00	51.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,912.95</b>	<b>5,376.00</b>	<b>6,536.95</b>	<b>54.87</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,912.95</b>	<b>4,300.00</b>	<b>7,612.95</b>	<b>63.90</b>
<b>+ Car Rental (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>Nett Liability (S\$)</b>		<b>4,700.00</b>		

### INSPECTION

Date of Assignment:	01/09/2020	
Date Inspected:	01/09/2020 Inspected At:	Advance Auto Garage (HQ) 23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE Singapore 415933
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 12 Oct 2020)
<b>Parts:</b>	143	BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJB1515X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER LOGO	Necessary	75.00 FL	*75.00 FL
2	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	225.00 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	385.00 FL	*- FL
4	2		*FRONT BUMPER SIDE HOLDER	Not Necessary	150.00 FL	*- FL
5	1		*FRONT BUMPER TOW COVER	Not Necessary	35.00 FL	*- FL
6	2		*FRONT BUMPER SIDE GRILLE	Not Necessary	170.00 FL	*- FL
7	2		*FRONT BUMPER FOG LAMP	Not Necessary	702.00 FL	*- FL
8	1		*FRONT BUMPER SPONGE	Not Necessary	128.00 FL	*- FL
9	1		*HEADLAMP	N/S Cracked	4,410.00 FL	*2,205.00 FL
10	1		*BONNET	Not Necessary	1,281.00 FL	*- FL
11	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
12	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
13	1		*FRONT BUMPER C/W SPOILER	Deformed	2,200.00 FS	*1,700.00 FS
14	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
15	1		*SET FRONT BUMPER STICKER WRAP	Necessary	480.00 FS	*380.00 FS
16	2		*FRONT GRILLE	Cut	500.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,891.00</b>	<b>4,810.00</b>
<b>- List Item Discount on L Items 5.00/5.00% (\$\$)</b>	378.05	114.00
<b>Total Parts (\$\$)</b>	<b>10,512.95</b>	<b>4,696.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	600.00	300.00
2	SPRAY PAINTING TO AFFECTED AREA	New	600.00	250.00
3	WIRING CHECK	New	50.00	30.00
4	TO PERFORM DIAGNOSTIC TEST	New	150.00	100.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,400.00</b>	<b>680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >