

# SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

TP Budget Direct.  
Xiao Chen.

02 September 2020

## QUOTATION FOR ACCIDENT REPAIR OF SLX8072X TOYOTA ALTIS

THIRD PARTY INSURER: Auto & General Insurance (Singapore) Pte Ltd

| S/No.                    | Parts List                                               | Qty | Amount (\$)               |
|--------------------------|----------------------------------------------------------|-----|---------------------------|
| 1.                       | Rear boot lid <i>Repair</i>                              | 1   | \$ 791.50 <i>X</i>        |
| 2.                       | Rear boot lid "logo" emblem                              | 1   | \$ 37.40 <i>✓</i>         |
| 3.                       | Rear boot lid "Corolla" emblem                           | 1   | \$ 37.80 <i>✓</i>         |
| 4.                       | Rear boot lid "Altis" emblem                             | 1   | \$ 38.90 <i>✓</i>         |
| 5.                       | Rear boot lid "1.6" emblem                               | 1   | \$ 39.90 <i>✓</i>         |
| 6.                       | Rear boot lid weather strip <i>3 New</i>                 | 1   | \$ 201.30 <i>+</i>        |
| 7.                       | Rear boot lid mechanism lock <i>new</i>                  | 1   | \$ 191.60 <i>+</i>        |
| 8.                       | Rear boot lid lock striker <i>new</i>                    | 1   | \$ 55.00 <i>+</i>         |
| 9.                       | Rear bumper <i>Repair</i>                                | 1   | \$ 561.60 <i>✓</i>        |
| 10.                      | Rear bumper side retainer L/R <i>new</i>                 | 2   | 61.45 \$ 122.90 <i>✓</i>  |
| 11.                      | Rear bumper corner retainer L/R <i>new</i>               | 2   | 60.25 \$ 120.50 <i>+</i>  |
| 12.                      | Rear bumper side reflector L/R <i>new</i>                | 2   | 130.55 \$ 261.10 <i>+</i> |
| 13.                      | Rear bumper inner sponge & reinforcement beam <i>new</i> | 1   | \$ 231.40 <i>✓</i>        |
| 14.                      | Rear bumper impact bracket L/R <i>new</i>                | 2   | 130.15 \$ 260.30 <i>+</i> |
| 15.                      | Rear end panel <i>Repair</i>                             | 1   | \$ 781.40 <i>+</i>        |
| 16.                      | Rear end panel garnish <i>3 New</i>                      | 1   | \$ 189.90 <i>+</i>        |
| 17.                      | Rear end panel garnish clip                              | 4   | 3.60 \$ 14.40 <i>+</i>    |
| Subtotal before discount |                                                          |     | \$ 4718.30                |
| Discount 25%             |                                                          |     | \$ 1179.57                |
| Subtotal 1               |                                                          |     | \$ 3538.72                |

1069.50  
802.42

| S/No.      | Parts S/Nett                      | Qty | Amount (\$)          |
|------------|-----------------------------------|-----|----------------------|
| 1.         | Rear bumper clip <i>new</i>       | 1   | \$ 30.00 <i>✓</i>    |
| 2.         | Rear reverse sensor <i>Repair</i> | 1   | \$ 300.00 <i>200</i> |
| 3.         | Rear end panel sealant <i>new</i> | 1   | \$ 50.00 <i>+</i>    |
| Subtotal 2 |                                   |     | \$ 380.00            |

230

## Labour

To check wiring

\$ 80 *30*

To remove, replace and reinstall rear reverse sensor

\$ 120 *50*

To remove and reinstall rear interior trims, garnish, seat, etc for necessary repairs

\$ 150 *50*

To straighten, repair, realign on front & rear affected area and replace damaged parts

\$ 800 *500*

\$ 800 *600*

Total Labour Cost

\$ 1950

1230

LKK Auto Consultants hereby certify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Cost Of Repairs (Total cost of parts + Total labour cost)

\$ 5868.72

total: 2262.42  
L/S: 1.8K.

Adrian L  
1/s 03/09/20  
04 Days