



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2007797
INV Date 19/11/2020
Reference CC4/EQI20009352/Ugs3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. GBF 6344M
Insured Veh. SJE 9073K
Claim No. DM20HO01265-JG
Policy No. DMPPHQ20-002840
Accident Date 17/08/2020
Inspection Date 03/09/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI20009352/Ugs3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 19-11-2020		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJE 9073K	Veh. Inspected	GBF 6344M
	Policy No.	DMPPHQ20-002840	Coverage (\$)	0.00
	Claim No.	DM20HO01265-JG	Excess (\$)	0.00
	Assign From	JOEL	Assign Date	02/09/2020
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN CABSTAR	c.c	2953
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JN1SC2F24Z0859175	Colour	GOLD
	Odometer	71224	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	YOKOHAMA	6 mm
	L/H Front Tyre	195 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	165 R13 (D)	CONDOR	6/6 mm
	L/H Rear Tyre	165 R13 (D)	CONDOR	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/08/2020	Inspection Date	03/09/2020
	Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 6344M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH HEADLAMP (N)	* CHECK	518.50	-
1	FRT RH SIDE STEP(N)	* CHECK	151.10	-
1	FRT RH DOOR (N)	TO REPAIR SEE LABOUR	1,474.10	-
1	FRONT BUMPER (N)	GRAZED	954.70	954.70
1	FRT DOOR SIGNAL LAMP O/S (NPA)	BROKEN	-	-
	LESS 20% DISCOUNT		-619.68	-190.94
			2,478.72	763.76
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<u>LABOUR</u>			
	LABOUR CHARGES TO RENEW FRT RH DOOR ,RENEW FRT RH CORNER PANEL & FRT BUMPER .INCLUSIVE OF THE REPAIR OF FRT RH DOOR .		1,170.00	585.00
	CHARGES TO SPRAY PAINTING SAME.		500.00	450.00
	RENEW RH HEADLAMP AND FOCUS .		48.00	48.00
	SUPPLY LTA STICKER .		15.00	15.00
	APPLY SEALANT TO FRT RH DOOR .	NOT NECESSARY	100.00	-
			1,833.00	1,098.00
	GRAND TOTAL		4,361.72	1,861.76
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$535.68 NETT)			1,861.76

Report Ref No. CC4/EQI20009352/Ugs3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 6344M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

