

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 68467483

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0234/20
DATE : 17-AUG-2020

EQ INSURANCE COMPANY LIMITED
108 ROBINSON ROAD
#06-01 G/MG BLDG
S(068900)
TEL : 62239433
FAX : 62243903

OWNER'S NAME : YEO YEW HOCK
ADDRESS : BLK 54 CASSIA CRESCENT
#02-125
REGN : BLK 13 HAIG ROAD #01-46 S(430013) S(390054)
TELEPHONE NO : 96587156/98236189

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2070010382
VEHICLE NO : GBF6344M
MODEL CODE : SWS2RBFF24MHV-AA-A
MODEL/YEAR : CABSTAR 3.0 5MT ABS AIRBAG EU5
ENGINE NO : ZD30014745N
CHASSIS NO : JN1SC2F24Z0859175
MILEAGE : 70150 KM
DATE IN : 17/08/2020
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 17/08/2020

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- 9645 0084 elmer@fanehong.com

not Authorized

LMR

3/8/20

3 days.

The ph. between party.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBF6344M

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO RENEW FRT RH DOOR, RENEW FRT RH CORNER PANEL & FRT BUMPER	1170.00	585
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	500.00	450
3	ZZ/003	RENEW RH HEADLAMP AND FOCUS	48.00	✓
4	ZZ/004	SUPPLY LTA STICKER	15.00	✓
5	ZZ/005	APPLY SEALANT TO FRT RH DOOR	11 100.00	X
TOTAL LABOUR CHARGES			1833.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBF6344M

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 RH HEADLAMP	26010-MA00A	518.50	?	
2 SUNDRIES	NPN		17	50.00 X
3 FRT RH SIDE STEP	96112-MA00A	151.10	?	
4 FRT RH DOOR	H0100-MA0MM	1474.10	R	X
5 FRONT BUMPER	62010-MD80A	954.70	grand	
SUB TOTAL		3098.40	0.00	50.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		929.52	0.00	5.00
GRAND TOTAL		2168.88	0.00	45.00
OVERALL TOTAL		2213.88		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

fnt door signal lamp o/s 320-

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBF6344M

TOTAL LABOUR CHARGES	1833.00
TOTAL SPARE PARTS CHARGES	2213.88

GRAND TOTAL	4046.88 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.