

Not Authorised
L1 Smp & 21001

AAD2008-123

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9860J

02 SEP 2020

SHD 9860J

VF1ABL15AUC277376

RENAULT

LATITUDE

28.8.2020

AM

9/5/2014

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

	PART
1	DOOR PANEL FRT LH
1	DOOR WEATHERSTRIP FRT LH
1	DOOR MOULDING BLACK FRT LH
1	DOOR MIRROR ASSY LH
1	DOOR HANDLE OUTER FRT LH
1	DOOR HINGE UPPER FRT LH
1	DOOR HINGE LOWER FRT LH
1	DOOR CHECK FRT LH
1	ROCKER PANEL INNER GARNISH LH
1	ROCKER PANEL OUTER LH
1	DOOR PANEL REAR LH
1	DOOR SEAL REAR LH
1	DOOR WEATHERSTRIP REAR LH
1	DOOR GLASS RUNNER SEAL REAR LH
1	DOOR HINGE UPPER REAR LH
1	DOOR HINGE LOWER REAR LH
1	FENDER PANEL FRT LH
1	WHEELARCH FRT LH
1	FENDER BRACKET FRT LH
1	HEADLAMP LH
1	BONNET HINGE LH
1	BONNET
1	RADIATOR GRILLE
1	RADIATOR GRILLE FRAME
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT LH
1	BUMPER UNDERTRAY FRT

	LIST
\$	R 2,844.66
\$	SL 316.00
\$	SL 100.50
\$	SL 1,483.40
\$	SL 169.50
\$	R 274.50
\$	R 300.55
\$	SL 90.90
\$	SL 466.51
\$	R 1,184.99
\$	R 2,844.66
\$	SL 119.80
\$	SL 311.60
\$	SL 320.90
\$	R 241.60
\$	R 169.90
\$	R 437.10
\$	SL 191.40 X
\$	SL 106.40 X
\$	my CM 743.60
\$	R 236.50
\$	R 1,312.70
\$	SL 969.90
\$	SL 686.00
\$	R 747.20
\$	SL 344.70
\$	SL 394.68
\$	SL 101.40
\$	SL 292.50

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9860J**AAD2008-123**

- 1 AIR CLEANER LOWER
- 1 AIR CLEANER HOSE
- 1 AIR CLEANER BOX

\$	<i>Sn</i>	271.26	X
\$	<i>Sn</i>	175.85	X
\$	<i>Sn</i>	464.20	X
TOTAL		\$ 18,715.36	
10%		\$ 1,871.54	
		\$ 16,843.82	

Special Nett

- 1 FRONT DOOR STICKER 'Trans-Cab'
- 1 FRONT DOOR STICKER 'Classic'
- 1 REAR DOOR STICKER '6555-3333'
- 1 LH SIDE RENAULT TYRE 215/60/16
- 1 LH SIDE RENAULT TYRE RIM
- 1 ROCKER PANEL CLIP
- 1 DOOR SEAL CLIP
- 1 BUMPER RETAINER CLIP
- 1 WHEELARCH CLIP FRT
- 1SET RADIATOR GRILLE FRAME CLIP
- 1SET BUMPER CLIP FRT
- 1SET RADIATOR GRILLE SCREW

\$	<i>na</i>	80.00	<i>608AL</i>
\$	<i>na</i>	80.00	<i>155AL</i>
\$	<i>na</i>	100.00	<i>608AL</i>
\$	<i>Sn</i>	330.00	} X
\$	<i>Sn</i>	380.00	
\$	<i>na</i>	65.00	
\$	<i>na</i>	65.00	
\$	<i>na</i>	60.00	
\$	<i>na</i>	60.00	
\$	<i>na</i>	60.00	
\$	<i>na</i>	70.00	
\$	<i>na</i>	55.00	
TOTAL		\$ 1,405.00	

TOTAL PARTS \$ 18,248.82**LABOUR**

To transfer of Rear door fittings, attachment and perform water seepage test.

\$ 170.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 X

To remove and refit interior fittings, trimings, garnish, fittings and others, to enable repair.

\$ 380.00 X

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 1,500.00 *500*

Trans-cab Auto Services Pte Ltd**AAD2008-123**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9860J

To rust-proofing and apply undercoat of the affected areas.	\$	240.00	301
Putty and spray painting of the affected portion.	\$	1,500.00	8801
To transfer of Front door fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	29
To transfer of Fender fittings, attachment and perform water seepage test.	\$	170.00	X
TOTAL	\$	4,690.00	
Over All Total	\$	22,938.82	

LUMP SUM (REPAIR DAY)**20 DAYS****3 days****For Official Use**Prepared By : _____
(Accident Dept)Verify By : _____
(Accident Workshop)Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: